



David J. Johnson
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

May 16, 2022

TO: All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD Advance Notice
Safety Recall 22S33**
Certain 2020 Model Year Escape PHEV Vehicles
Certain 2021 Model Year Corsair PHEV Vehicles
High Voltage Battery Replacement

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Corsair	2021	LAP	September 18, 2020 through September 18, 2020
Escape	2020	LAP	July 21, 2020 through August 4, 2020

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

In some of the affected vehicles, the High Voltage (HV) battery can unexpectedly lose power. If the HV battery loses power, it will cause the vehicle to display a “Stop Safely Now” message on the instrument panel and loss of motive power causing the vehicle to coast to a stop. A sudden loss of motive power can increase the risk of a crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers early third quarter when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink that reads "D. Johnson". The signature is written in a cursive style with a large, stylized initial "D".

David J. Johnson