

Part 573 Safety Recall Report

22V-336

Manufacturer Name : Kuntry Kustom RV, LLC

Submission Date : MAY 24, 2022

NHTSA Recall No. : 22V-336

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Kuntry Kustom RV, LLC

Address : 423 S. Main St.
Topeka, IN 46571

Company phone : 593-2208

Population :

Number of potentially involved : 172

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2017-2020 Rich Specialty Trailers Sanitation, Movie, Office, Bunk House

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Supplier provided component with possibly defective. Supplier provided dates and serial codes of affected parts. Supplier provided total number of purchased components that could have been installed in the products. 172 possible defective regulators used in LP gas systems in trailers.

Production Dates : JAN 01, 2017 - JUN 30, 2020

VIN Range 1 : Begin : 1k9bu2429h1236065 **End :** 1k9bu2025l1236238

☐ Not sequential

Description of Defect :

Description of the Defect : LP regulator may fail.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Failure of the LP regulator may cause an excessive flame in LP appliance and in certain conditions may ignite adjacent materials resulting in a fire.

Description of the Cause : Failure of installed component Winntec model 6020 two stage propane regulators.

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Winntec model 6020 regulator

Component Description : LP regulator

Component Part Number : 6020 Regulator

Supplier Identification :

Component Manufacturer

Name : UFP Distribution

Address : 2701 ADA Dr

Elkhart Indiana 46514

Country : United States

Chronology :

Jan 4th 2022-Notified by NHTSA of possible safety defect.

Feb 8th 2022-Reviewed service records and while no reports of injury, no deaths, no field reports of problems and no regulator problems the decision is made to recall.

May 12th 2022- Received notice from supplier that the replacement component/regular is back in stock so can now offer replacement part.

May 13th 2022- Submitted letter and notice to NHTSA

Description of Remedy :

Description of Remedy Program : Identify, confirm, and replace possible defective part at no charge and reimburse labor costs for replacement.

How Remedy Component Differs from Recalled Component : Possible defective part will be replaced with new LP regulator from a different component manufacturer.

Identify How/When Recall Condition was Corrected in Production : Stopped use of this defective component approximately two years ago.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 17, 2022 - MAY 24, 2022

Planned Owner Notification Date : MAY 17, 2022 - MAY 24, 2022

* NR - Not Reported