OMB Control No.: 2127-0004

Recall Quarterly Report

22V-340

Manufacturer Name: Daimler Trucks North America, LLC **NHTSA Recall No.** / **MFR Recall No.**: 22V-340 /FL934

Recall Subject: Rotary Shifter May Unintentionally Shift to Drive

Owner Notification Beginning Date: JUN 07, 2022

Owner Notification End Date: JUN 07, 2022



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 3 | JAN 28, 2023 | 2022-4 | 23 | 19 | 0 | 0 |
| 2 | OCT 28, 2022 | 2022-3 | 23 | 19 | 0 | 0 |
| 1 | JUL 28, 2022 | 2022-2 | 23 | 19 | 0 | 0 |

This Document Last Updated: JAN 31, 2023

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.