
IMPORTANT SAFETY RECALL SAFETY RECALL 22E-003

"This notice applies to your vehicle"

2022 Reiser Trailer

Vin shown (VEHICLE IDENTIFICATION NUMBER):





WHATS THE ISSUE? THE COUPLER ON THE INSIDE MAY ONLY BE TACKED.

WHATS AT RISK? THE COUPLER COULD FAIL

COURSE OF ACTION? PLEASE SEE THE PHOTOS AND CHECK YOUR COUPLER TO VERIFY THAT THE WELD IS COMPLETE. IF YOU ARE UNABLE TO LOOK AT IT, PLEASE NOTIFY YOUR DEALER AND MAKE ARRANGMENTS TO GET IT INSPECTED. IF IT IS FOUND DEFECTIVE CONTACT YOUR DEALER TO MAKE ARRANGMENTS TO GET THE COUPLER REPLACED. Any (inspection or need replacement will be done at no charge to you)

We have not and do not expect to find any defective couplers. We are just being extra cautious.

Please contact us immediately.

Reiser Mfg Co Inc

4571 Millrock Rd

New Waterford, Oh 44445

330.846.8003

lori@reisertrailers.com

Marled 6/27

I did sent a copy of this To NHTSA?

Our dealer contacted this customen As well as us via phone and email we sent this and another follow up and finally he called back of Coupler is OK-