

Part 573 Safety Recall Report

22V-377

Manufacturer Name : McNeilus Truck & Manufacturing, Inc.**Submission Date :** JUL 05, 2022**NHTSA Recall No. :** 22V-377**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : McNeilus Truck & Manufacturing, Inc.

Number of potentially involved : 792

Address : 524 County Road 34 East

Estimated percentage with defect : 100 %

P.O. Box 70 Dodge Center MN 55927

Company phone : 507-374-6321

Vehicle Information :

Vehicle 1 : 2020-2022 McNeilus STD mixer/Bridgemaster

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : DIESEL

Descriptive Information : The recall population includes all McNeilus STD and Bridgemaster concrete mixers produced at the London, Ontario facility.

Production Dates : JUL 01, 2020 - APR 01, 2022

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The affected vehicles may be missing one or more safety decals which provide instructions to the operator on the proper operation of the vehicle, the mixer and other functions. The number and type of safety decals missing vary depending on the build options for each individual vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Without the safety decals, the operator may not be aware of information related to the operation of the vehicle, the mixer and/or other functions which may increase the risk of an injury.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

In March 2022, McNeilus implemented an updated vehicle inspection process for end of the line vehicle inspection. As part of this updated process, McNeilus identified that certain vehicles did not have all of the safety decals applied that were associated with the individual vehicle build options. Vehicles at the facility were reworked to correct the issue. Upon further investigation, McNeilus found that a change in the processes at the manufacturing facility related to the application of the individual decals had taken place in July 2020, and as a result there was a possibility that vehicles manufactured from that point forward may not include all safety decals. On May 19, 2022, McNeilus determined that the condition created the potential for an increased risk of injury and decided to conduct a recall to update the vehicles in the field.

Description of Remedy :

Description of Remedy Program : Vehicle owners will be advised to conduct an inspection for any missing decals based on the individual vehicle build options. McNeilus will provide any additional decals needed free of charge and will provide warranty reimbursement for the inspection.

How Remedy Component Differs from Recalled Component : Following the remedy, the vehicle will have any missing safety decals applied.

Identify How/When Recall Condition was Corrected in Production : Updated work instructions were implemented in April 2022 to ensure that the vehicle receives all of the safety decals associated with the vehicle build options.

Recall Schedule :

Description of Recall Schedule : Notifications to customers will be made via a customer letter. The 577

Planned Dealer Notification Date :

customer letter will be mailed pending NHTSA approval. McNeilus does not distribute vehicles through dealers.

NR - NR

Planned Owner Notification Date :

JUL 18, 2022 - JUL 21, 2022

* NR - Not Reported