

# Part 573 Safety Recall Report

# 22V-389

**Manufacturer Name :** TM Industries**Submission Date :** MAY 31, 2022**NHTSA Recall No. :** 22V-389**Manufacturer Recall No. :** 4T9T**Manufacturer Information :**

Manufacturer Name : TM Industries

Address : 42021 268th Street

Parkston SD 57366

Company phone : 605.951.7580

**Population :**

Number of potentially involved : 10

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2021-2022 TrailManor 2518 series

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : NR

**Descriptive Information :** How recall units were determined. Data Card with model numbers. How they differ?  
Different model numbers.

We received 10 of these models from Dometic Corporation Model number CE99-ZF.

Production Dates : DEC 29, 2021 - APR 13, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** The 2 burner cook tops installed in these units may have incurred abrasions internally on the metal sealing surface of the burner control valve

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Increased risk of fire and injury. There is a potential for the gas leak behind the control nob to ignite and create a small flame and present the possibility of a burn to the user.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Involved Components :**

Component Name 1 : Dometic model number CE99-ZF-US

Component Description : 2 burner cooktop

Component Part Number : 9600037307

## Supplier Identification :

### Component Manufacturer

Name : Dometic Corporation

Address : 2320 Industrial Parkway  
Elkhart Indiana 46516

Country : United States

## Chronology :

We were notified by Dometic about the NHTSA recall of the affected two burner cooktop.

## Description of Remedy :

Description of Remedy Program : Schedule a appointment with a certified Dometic RV dealer. They will contact Dometic and will do the repair and replacement at no cost to the enduser.

How Remedy Component Differs from Recalled Component : We only had 10 of the above identified cook tops.

Identify How/When Recall Condition was Corrected in Production : We are no longer using that particular model cooktop.

## Recall Schedule :

Description of Recall Schedule : Dealer letter sent out on May 16, 2022. emails also sent to all dealers.

Planned Dealer Notification Date : MAY 30, 2022 - JUN 30, 2022

Planned Owner Notification Date : MAY 30, 2022 - JUN 30, 2022

\* NR - Not Reported