

Part 573 Safety Recall Report

22V-393

Manufacturer Name : Winnebago Industries, Inc.**Submission Date :** AUG 29, 2022**NHTSA Recall No. :** 22V-393**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc.

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 56

Estimated percentage with defect : 40 %

Vehicle Information :

Vehicle 1 : 2020-2020 Winnebago ERA

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : PO's and productions records

Production Dates : MAY 26, 2021 - APR 27, 2022

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The burner control valve, mated directly to the control knob via the valve stem, may leak gas. This gas will leak directly into the recessed portion of the cooktop, where the knobs and ignitor are located, and may be ignited by the active burner(s). The ignition will result in a small pilot flame directly at control knob

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An increased risk of injury and fire.

Description of the Cause : Reference Recall 22E-021

Identification of Any Warning NR
that can Occur :**Involved Components :**

Component Name 1 : Cook top

Component Description : Cook top

Component Part Number : CE99-ZF and PI8022

Supplier Identification :

Component Manufacturer

Name : Dometic Corporation

Address : 5155 Verdant Drive
Elkhart Indiana 46516

Country : United States

Chronology :

- 5-13-22 E-mail from Dometic telling us of pending recall 22E-021
- 5-23-22 Questioned Dometic on non-vadid S/N looking for a complete list
- 5-25-22 Dometic can not provide complete S/N list of products sent to us
- 5-26-22 We can can't search by S/N so we check date range using POs
- 6-2-22 Submit 573 notice on NHTSA portal.

Description of Remedy :

Description of Remedy Program : Defer to Dometic for their remedy reimbursement program. Remedy will be made by replacement/exchange with newer cooktops that are not within the recall population. Remedy replacement will be completed at no cost to the end user. The user will indicate that they have an affected cooktop and supply the serial number information to Dometic Corporation. The remedy replacement unit will be sent with instructions to complete the installation and functional verification at no cost to the end user by a qualified RV technician. Reimbursement to the qualified RV technician will be provided once Dometic Corporation receives the recall response card and recalled unit documenting that the replacement has been made. Units still in inventory at RV OEM's and dealers will be replaced at no charge with like units.

How Remedy Component Differs from Recalled Component : Defer to Dometic 22E-021
The replacement/exchange unit will have a completely different serial number outside of the recall population that will not have the defective

burner control valve. The units will be visually the same to the end user.

Identify How/When Recall Condition was Corrected in Production : Dometic sates we have good product in inventory

Recall Schedule :

Description of Recall Schedule : Dometic letter will go out with our cover letter this month
Planned Dealer Notification Date : JUN 30, 2022 - JUN 30, 2022
Planned Owner Notification Date : JUN 30, 2022 - JUN 30, 2022

* NR - Not Reported