IMPORTANT SAFETY RECALL



NHTSA RECALL: 22V395 CANADA RECALL: 2022-289 FR ID: 51-1519

<<CITY>>, <<ST>> <<ZIP-XXX>>

<<DEALERNAME>>

<<ADDRESS>>

DEPARTMENT OF COMPLIANCE VEHICLE SAFETY AND RECALL MANAGEMENT BUILDING 11 423 N MAIN ST MIDDLEBURY, INDIANA 46540-9218

o Integrity

Safety

o Quality

Customer Service

July 5, 2022

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

"It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law." —Forest River motorized and towable products are contained in this section-

CANADA: Pursuant to the Canadian Motor Vehicle Safety Act, section 5

<u>Companies who sell new non-complying vehicles may be in violation of the Motor Vehicle Safety Act. Substantial</u> <u>penalties apply to violations of this law. This notice is being sent to you in accordance with the requirements of the Motor</u> <u>Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.</u>

Forest River has decided that a safety defect exists in certain 2022 East to West Alta and Palomino SolAire travel trailer recreational vehicles. Forest River is recalling the defect model(s) to ensure the safety of our future retail consumers and your dealership. Forest River apologizes for any inconvenience this action may cause your dealership; however, safety continued satisfaction and our commitment to building great products are of the utmost importance to Forest River.

The identified VIN referenced in the attached document(s). The designated Date range of production is: Palomino SolAire 2/18/2022 through 4/30/2022 East to West Alta 1/25/2022 through 5/24/2022

DEFECT/NONCOMPLIANCE:

Per the component suppliers recall, 22E042: The affected units with this dinette table may have incomplete welds that do not hold the weight rating required for this unit. If the welds break, the table could drop down when in the upright or closed position.

EVALUATION OF RISK:

Per the component suppliers recall, 22E042: "The table could potentially drop down in the upright or closed position." Which could result in personal injury.

SERVICE PROCEDURE:

Dealership Service Department procedures for addressing the table can be found on Dealer Connect

WHAT IS THE PART NUMBER OF THE REMEDY KIT?

East to West Part Number F100229728 Palomino Part Number F100185477

Prior authorization is required for this remedy.

DEALER REPAIR CODES: Dealer Connect

UNITED STATES	CANADA	REPAIR CODE	DESCRIPTION	ALLOWABLE HOUR(S)
22V395	2022-289	RC-090-01-00-004202	REPLACE DINETTE TABLE	0.30

IMPORTANT SAFETY RECALL

HELPFUL CONTACT INFORMATION:

CONTACT	PHONE
East to West Alta Customer Service	(574)-264-6664
Palomino SolAire Customer Service	(269)-432-3721

The Recall shall be considered the utmost priority to remedy the 2022 East to West Alta and Palomino SolAire travel trailer in question. **The retail consumer shall not be charged** any amount of monies for remedy to their 2022 East to West Alta and Palomino SolAire travel trailer listed under this Recall.

If your dealership has already performed the remedy to the 2022 East to West Alta and Palomino SolAire travel trailers, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s). If the remedy needs to be performed on an out of warranty East to West Alta and Palomino SolAire travel trailers in which the VIN falls under as stated in the identified VIN listing, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s).

Notice:

In no manner shall a Forest River Product Owner or Coachmen Product Owner be charged any fee(s) for scheduling, conduction or completion of the recall. Additionally, all dealership(s) that are Forest River and/or Coachmen dealership(s) are Federally Mandated to perform the recall once presented with this recall whether by the Owner or Dealership receipt of this letter, without denial of service to the Owner. Lastly, denial of a remedy for this recall is a Federal Violation punishable by law resulting substantial fines and/or civil penalties.

Federal Regulation requires that any lessor receiving this Recall must forward a copy of this notice to the lessee within ten days. If your dealership no longer owns this vehicle, please inform the Warranty Manager of the product listed above of the change of ownership.

Sincerely, Forest River, Inc. LLC Office of Corporate Compliance