

# Part 573 Safety Recall Report

# 22V-397

**Manufacturer Name :** Kawasaki Motors Corp., U.S.A.**Submission Date :** JUN 06, 2022**NHTSA Recall No. :** 22V-397**Manufacturer Recall No. :** MC22-04**Manufacturer Information :**

Manufacturer Name : Kawasaki Motors Corp., U.S.A.

Address : PO Box 25252

Santa Ana CA 92799-5252

Company phone : 949-770-0400

**Population :**

Number of potentially involved : 1,923

Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2020-2022 Kawasaki Motors, Ltd. LX230A/G

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

**Descriptive Information :** The affected vehicles are certain 2020-2021 LX230A, 2022 LX230G models. The recall population was determined by the beginning and ending production date for the models affected: LX230A (Kawasaki/KLX 230 ABS/2020-2021): 1,220 Units. LX230G (Kawasaki/KLX 230 S ABS/2022) : 703 Units

**Production Dates :** JUN 17, 2019 - FEB 17, 2022

VIN Range 1 : Begin : MH4LXCA13LJP00012 End : MH4LXCA10MJP00955

 Not sequential

VIN Range 2 : Begin : MH4LXCG19NJP00042 End : MH4LXCG14NJP01096

 Not sequential**Description of Defect :**

**Description of the Defect :** On eligible units, a brake disc with a smaller than specified diameter designed for a different model, might have been installed on the front wheel. This configuration might not meet the technical requirement for braking performance under UN Regulation No. 78 / FMVSS No. 122.

FMVSS 1 : 122 - Motorcycle brake systems

FMVSS 2 : NR

**Description of the Safety Risk :** This could lead to insufficient braking force in severe braking conditions.**Description of the Cause :** Error in assembly of the front brake-disk.

**Identification of Any Warning that can Occur :** NR

**Involved Components :**

Component Name 1 : DISC

Component Description : Front Brake-Disc

Component Part Number : 41080-0701

## Supplier Identification :

### Component Manufacturer

Name : Kawasaki Motors, Ltd.

Address : 1-1 Kawasaki-cho

Akashi, Hyogo Foreign States 673-8666

Country : Japan

## Chronology :

- April 2022: Kawasaki Motors, Ltd (KHI) received a report from its Japanese distributor (KMJ) that there was a vehicle installed with a smaller than specified diameter brake disc on the front brake. KHI Quality Assurance Division started investigating.
- April 2022: KHI asked dealerships which received vehicles assembled on the same day as the problem vehicle to search for additional instances of the problem. Two more vehicles with same defect were found.
- April 2022: It was found that during the manufacturing process, the incorrect front brake disc assembly may have been used on September 1st and 7th. Only Japanese spec vehicles were assembled on those days.
- April 22, 2022 : KHI decided to initiate a recall campaign for the Japanese market to address this issue.
- April 25, 2022: KMC informed NHTSA that KHI had initiated a foreign recall for certain of these models.
- May 2022: KHI received a report from KMJ that there was another vehicle with the same defect from outside of the initially identified range, which was the range recalled in the Japanese market.
- June 1, 2022 : KHI decided to recall all vehicles of this model to be sure that it completely addressed this issue.

## Description of Remedy :

Description of Remedy Program :	The front brake disc will be replaced with the correct one (41080-0709), and the brake pads will also be replaced with a new set. The plan of reimbursement will be described on the owner's letter as follows: If you have experienced the failure described above prior to receiving this letter and have paid to have it corrected, you may be eligible for full or partial reimbursement for your documented cost of repair(s). To apply for reimbursement, please send copies of current owner and VIN information along with copies of repair orders and payment confirmation to the following address: Kawasaki Motors Corp., U.S.A. ATTN: Customer Care P. O. Box 25252 Santa Ana, California 92799-5252
How Remedy Component Differs from Recalled Component :	The difference can be identified by diameter of the front brake-disc. LAX230A/G(ABS): 265mm, LX230b/d(Non-ABS) and LX230E/F(Non-street): 240mm.
Identify How/When Recall Condition was Corrected in Production :	Similar parts will be further separated to avoid picking of the wrong parts. A check process will also be added at final inspection to confirm the diameter of the front brake-disc. An inspection will be added at final inspection to confirm the specifications of the front brake disc. These countermeasures have been in effect since April 21, 2022.

## Recall Schedule :

Description of Recall Schedule :	KMC will distribute both electronic and paper copies of a Recall Service bulletin to all Kawasaki motorcycle dealers. KMC will mail the owner notification letter via U.S.P.S. enclosed in an envelope with the statement "Important Recall Safety Information" printed on the outside of the envelope.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

\* NR - Not Reported