

Part 573 Safety Recall Report

22V-422

Manufacturer Name : Lamborghini (Automobili Lamborghini)

Submission Date : JUN 16, 2022

NHTSA Recall No. : 22V-422

Manufacturer Recall No. : L62X-R.03.22



Manufacturer Information :

Population :

Manufacturer Name : Lamborghini (Automobili Lamborghini)
Address : Via Modena 12
 Sant'Agata Bolognese (BO) 40019 -
 Italy 00 99999
Company phone : 999

Number of potentially involved : 21
Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Automobili Lamborghini Huracan EVO and STO

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Basis for determination was made according to manufacturing records.

Production Dates : MAY 02, 2022 - MAY 09, 2022

VIN Range 1 : Begin : ZHWUA6ZX6NLA20125 End : ZHWUT5ZF9NLA20227 Not sequential

Description of Defect :

Description of the Defect : The left door outside handle may not have been properly assembled. The safety clip of the cable that unlatches the door when the outer handle is pulled may have not been properly positioned. As a result, over time, the cable could become loose and the left-side doors may not be able to be opened from outside of the vehicle.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : It might not be possible to open the unlocked door on the left side by using the outside door handle, posing an entrapment risk. This failure could lead to the inability to operate the handle from outside of the vehicle which, in the event of an emergency, may increase their risk of injury. The door can be opened from inside at any time.

Description of the Cause : Due to a production deviation during the assembly of the component, the security lock of the bowden cable may have not been properly engaged.

Identification of Any Warning that can Occur : The customer will not receive an advance warning due to the nature of the failure mechanism.

Involved Components :

Component Name 1 : Door handle bowden cable

Component Description : Door handle bowden cable safety clip

Component Part Number : 4T2837885

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On May 2022 during end of line quality checks Automobili Lamborghini S.p.A. identified a case where the safety clip at the end of opening Bowden cable, was not correctly rotated and engaged.

Automobili Lamborghini S.p.A. immediately launched an internal investigation to determine the scope of this topic and the root cause. In the course of the investigation it was determined that the deviation was traceable to human error during the specific step of the assembling process.

Results from the investigation revealed a risk that a number of vehicles produced between April 15th 2022 and May 17th 2022 may present the issue.

A plant campaign was launched to contain potentially affected vehicles. However, some potentially affected vehicles had already been released to the markets.

On June 10th 2022 the matter was presented at the Product Safety Committee which determined that a potential safety risk cannot be ruled out and decided to conduct a voluntary safety recall.

Lamborghini is not aware of any warranty claims or customer claims due to this issue.

Description of Remedy :

Description of Remedy Program : Automobili Lamborghini S.p.A. will notify all owners of affected vehicles and will instruct them to arrange for an appointment with an authorized Lamborghini dealer. Dealers will check the safety clip positioning and correct it if necessary, free of charge. Lamborghini will not offer a reimbursement plan for this campaign as all involved vehicles are new and would be covered under the manufacturer's warranty program.

How Remedy Component Differs from Recalled Component : The door handles have guaranteed correct engagement of the bowden cable safety clip after the inspection.

Identify How/When Recall Condition was Corrected in Production : Vehicles produced from May 17th 2022 have since been inspected for properly bowden cable safety clip engagement and the assembly process was revised and improved in order to prevent unknown variables.

Recall Schedule :

Description of Recall Schedule : Customers will be notified by registered mail and customer app; while dealers through Lamborghini dealer portal.

Planned Dealer Notification Date : JUN 17, 2022 - JUN 17, 2022

Planned Owner Notification Date : JUL 01, 2022 - JUL 08, 2022

* NR - Not Reported