



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

June 23, 2022

Mr. David Mihalick  
Standards Compliance Manager  
Cruiser RV  
419 W. Pike Street  
Jackson Center, OH 45334

NEF-107KL  
22V-433

**Subject:** Cracked LP Gas Quick Disconnect Fitting

Dear Mr. Mihalick:

This letter serves to acknowledge Cruiser RV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

CRUISER/EMBRACE/2022  
CRUISER/MPG/2022  
CRUISER/RADIANCE ULTRA-LITE/2022  
CRUISER/SHADOW CRUISER/2022  
CRUISER/STRYKER/2022  
CRUISER/TWILIGHT/2022  
CRUISER RV/HITCH/2022

**Mfr's Report Date:** June 17, 2022

**NHTSA Campaign Number:** 22V-433

**Components:**

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER:LPG SYSTEMS:LINES AND FITTINGS

**Potential Number of Units Affected:** 2,985

**Problem Description:**

Cruiser RV (Cruiser) is recalling certain 2022 Shadow Cruiser, Embrace, MPG, Radiance, Hitch, Twilight, and Stryker travel trailers. The quick disconnect fittings in the LP gas system may be cracked, causing a gas leak.

**Consequence:**

A gas leak in the presence of an ignition source can increase the risk of a fire.

**Remedy:**

Dealers will inspect and replace the fittings, as necessary, free of charge. Owner notification letters are expected to be mailed in July 17, 2022. Owners may contact Cruiser customer service at 1-574-206-7920. Cruiser's number for this recall is 99.03.21.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Cruiser RV's contact for this recall will be Kristin Lepper who may be reached by email at [kristin.lepper@dot.gov](mailto:kristin.lepper@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement