

**Recall Quarterly Report****22V-452**

**Manufacturer Name :** Airstream, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 22V-452 /  
**Recall Subject :** Hub May Separate from Axle Wheel End  
**Owner Notification Beginning Date :** AUG 23, 2022  
**Owner Notification End Date:** AUG 23, 2022



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 3        | APR 26, 2023    | 2023-1         | 224               | 180            | 0                 | 5             |
| 2        | JAN 31, 2023    | 2022-4         | 224               | 178            | 0                 | 5             |
| 1        | OCT 21, 2022    | 2022-3         | 224               | 168            | 0                 | 5             |

This Document Last Updated : APR 27, 2023

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.