



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

July 12, 2022

Mr. Greg Gunther  
Department Manager VCA  
Mercedes-Benz USA, LLC  
13470 International Parkway  
Jacksonville, FL 32218

NEF-107ES  
22V-466

**Subject:** Front Air Bag May Deploy Improperly/FMVSS 208

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

MERCEDES-BENZ/GLS450/2020

MERCEDES-BENZ/GLS580/2020

**Mfr's Report Date:** July 1, 2022

**NHTSA Campaign Number:** 22V-466

**Components:**

AIR BAGS:FRONTAL

**Potential Number of Units Affected:** 81

**Problem Description:**

Mercedes-Benz, LLC (MBUSA) is recalling certain 2020 Mercedes-Benz GLS 450 and GLS 580 vehicles. The front air bag wiring harness may be routed incorrectly, which can cause the air bag not to deploy properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

**Consequence:**

An air bag that does not deploy properly can increase the risk of injury in the event of a crash.

**Remedy:**

Dealers will correct the wiring harness routing, free of charge. Owners notification letters are expected to be mailed August 30, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mercedes-Benz USA, LLC's contact for this recall will be Emily C. Smith who may be reached by email at [emily.c.smith@dot.gov](mailto:emily.c.smith@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement