IMPORTANT SAFETY RECALL

This notice applies to your vehicle

VIN:

Inspect Generator and Steering Wiring Harness Connections
NHTSA Recall ID: 22V491

August, 2022



- A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz Sprinter dealer as soon as possible.
- This repair will be provided free of charge.

Dear Mercedes-Benz Sprinter Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2021 Mercedes-Benz Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.



What is the issue?

The generator wiring harness may have been incorrectly connected to the electric power steering system wiring harness which can result in an electrical surge. An electrical surge can increase the risk of a fire.



What will your Mercedes-Benz Dealer do?

An authorized Mercedes-Benz Sprinter dealer will inspect the connection of the harnesses and correct it, if necessary. This could take approximately 1 hour.

This service will be provided free of charge. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.



Steps to take.

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz Sprinter dealer at your earliest convenience. To locate the nearest Mercedes-Benz Sprinter dealer, visit https://www.mbvans.com/en/dealers or call 1-800 FOR-MERCEDES (1-800-367-6372).

Please mention you are scheduling an appointment to inspect the generator and steering wiring harness connections under Recall Campaign #2022080003

A VIN-based recall lookup tool on our website offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. Please visit www.mbvans.com/en/recall-information. Should you have any questions, please contact your authorized Mercedes-Benz Sprinter dealer. We apologize for any inconvenience this may have caused and look forward to taking care of this important safety issue immediately.

Sincerely, Mercedes-Benz USA



Additional Information for Owners:

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

		IMPORTANT					VIN:						
If for any reason YOU NO the ENCLOSED ENVELOPE, contact them.													
□ EXPORTED □ LEASE, VEHICLE RE □ SCRAPPED □ SOLD □ STOLEN □ OTHER		_											
OR MY NEW NAME OF	R ADDRESS IS:												
Last Name, First Name													
Street				I I						Ap	ot		
												T	
City							Sta	ate	ZIF)			
			T									Τ	
Email Address				<u> </u>									
												1	
Phone (numbers only)				Mobile (n	umbers o	nlv)							
,				(.,							
Date		Signature							-				

**** PLEASE DO NOT DETACH. RETURN COMPLETE LETTER ****
DO NOT USE THE ENCLOSED ENVELOPE FOR OTHER CORRESPONDENCE

Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: (770) 705-0600

