Just a reminder that you're receiving this email because you have expressed an interest in Subaru of America. Don't forget to add us to your address book so we'll be sure to land in your inbox! You may <%@ include view='soaManagePreferences' %>.





Subaru Safety Recall WRE-22

NHTSA ID 22V522

Dear <%= targetData.firstName %>,

Your VIN <%= targetData.VIN %>

SUBARU OF AMERICA, INC. previously notified all affected vehicle

2015-2021 model year WRX STI vehicles.

We are writing to inform you that Subaru has recently made an update to the service procedure that optimizes the repair process and accommodates vehicles with most aftermarket exhaust assemblies.

owners of this recall by first class mail on September 16, 2022,

regarding a defect, which relates to motor vehicle safety, in certain

Descritpion of the Defect Your vehicle may contain a defective backup lamp switch, which may

cause the backup lamps to not illuminate, the rear-view camera (if

## equipped) to not display an image, and the select lever/gear position indicator in the combination meter to not display 'R' when driving in

reverse.

Safety Risk If the backup lamps do not illuminate when the vehicle is in reverse gear, this may reduce the awareness of other motorists or road users of the driver's intention to operate the vehicle in reverse, increasing the risk of a crash. Additionally, a rear-view camera that does not display an image can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

## switch with an improved one, at no cost to you.

What You Should Do

What Will Subaru Do

Please contact your Subaru retailer (dealer) immediately for an appointment to have this repair performed, at no cost to you.

Until this repair is performed, please use caution when driving in

Subaru will conduct an inspection and replace the backup lamp

surrounding area by turning your head rearward and/or using the mirrors and move backward at a slow speed.

reverse. You should always check the rear view and the

in scheduling.

**Owner Information** 

your information.

listed below.

<u>campaign.com</u>.

Find a Retailer

How Long Will the Repair Take The time it will take to inspect your vehicle is less than fifteen

minutes. If it is found that the switch needs to be replaced, the time for this repair is approximately two hours. However, it may be necessary to leave your vehicle for a longer period of time on the day

of your scheduled appointment to allow your Subaru retailer flexibility

Government regulations require that recall notifications be sent to the last known owner of record. That information is based primarily on state registration and title data. If you are a lessor of this vehicle, federal regulations require you to forward this notice to your lessee within ten days. If you have moved or sold your vehicle, please go to

https://www.subaru.com/support/customer-support.html to send us

If you have already paid for repairs associated with this condition, you

may be eligible for reimbursement. Reimbursement consideration will

be based on the amount an authorized Subaru retailer in your area

Please send the original service repair order, which has the name of the repair facility, date of repair, mileage at the time of repair, complete 17-digit vehicle identification number (VIN), and your name,

with correct mailing address and telephone number to the address

Subaru of America, Inc. Customer Advocacy Department, Attention: WRE-22 Recall P.O. Box 9103, Camden, NJ 08101-9877 Please send original receipts only and retain a photocopy for your records. Please be assured that we will attempt to process your

To locate the nearest Subaru retailer, you can access our website at

For additional information, please go to: <a href="http://www.wre22.service-">http://www.wre22.service-</a>

If you need additional assistance, please contact us directly:

• By U.S. Postal mail: Write us at Subaru of America, Inc.

## reimbursement request as quickly as possible, but it may take up to 60 days for this process to be completed.

www.subaru.com and select 'Find a Retailer.'

If You Need Further Assistance

8:00 a.m. and 7:00 p.m. ET

Attn: Customer Advocacy Department

to make the necessary repairs free of charge.

P.O. Box 9103, Camden, NJ 08101-9877

If You Have Previously Paid for a Repair

would charge for the same repair.

 By e-mail: Go to www.subaru.com and select "Customer Support" By telephone: 1-844-373-6614 Monday through Friday between

To subscribe to the NHTSA Recall Notification email System, please go to: <a href="https://www-odi.nhtsa.dot.gov/nhtsa/subscriptions">https://www-odi.nhtsa.dot.gov/nhtsa/subscriptions</a>. Please contact us immediately if the Subaru retailer fails or is unable

You may also contact the Administrator, National Highway Traffic

Safety Administration (NHTSA), 1200 New Jersey Ave., SE,

888-327-4236 (TTY: 1-800-424-9153) or go to <a href="http://www.NHTSA.gov">http://www.NHTSA.gov</a> if you believe the Subaru retailer has failed or is unable to remedy your vehicle without charge within a reasonable amount of time.

Your continued satisfaction with your Subaru is important to us.

Please understand that we have taken this action in the interest of

Washington, DC 20590 or call the toll-free Vehicle Safety Hotline at 1-

your safety and your vehicle's proper operation. We sincerely apologize for any inconvenience this matter may cause and urge you to schedule an appointment as soon as possible. Sincerely, Subaru of America, Inc.

America, Inc., visit our website at subaru.com/customer-support.html, or call (800) 782-2783. You received this message because you opted in to receive communications from Subaru of

Please do not reply to this message. To obtain information on how to contact Subaru of

America, Inc. We respect your privacy and if you prefer not to receive any future email messages from us,

Subaru of America, Inc., PO Box 9103, Camden, NJ 08101-9877

please <%@ include view='soaManagePreferences' %>.

© Subaru of America, Inc.