



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: 22V-604
Safety Advisory: 22-434
Lippert Components Recall: 22E-055
April 21, 2023

IMPORTANT SAFETY RECALL – 2nd Notice

«POLKNAME»
«POLKADDRESS»
«POLKCITY», «POLKST» «POLKZIPplus4»



This notice applies to your vehicle: «VIN»

Dear «POLKNAME»:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

**Our records indicate
YOUR UNIT HAS NOT BEEN
REMEDIED.
Please **DO NOT** ignore this notice!**

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2022 Aspen Trail, Carbon, Coleman, Colorado, Cougar, Hideout, Montana, Outback, Passport, Raptor, Retreat, Springdale, Sprinter, Voltage, Yukon, 2022-2023 Bullet, Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that vehicles in the recall population were built with a certain Lippert Electric Retractable Awnings, up to 18 feet in length, that the heat-welded seam may separate. Under certain conditions during use or travel the welded seam on the fabric may separate, potentially allowing the awning to drop beyond normal operation leading to an increased risk of personal injury.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to repair or replace affected awning fabrics. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

Inspect awnings for separation, separating awnings can be stowed before traveling to dealerships for repair. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 1/2 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

**BE ADVISED –
Damage caused by failure to have the
recall remedy completed will be the
responsibility of the owner.**

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.nhtsa.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

cc: National Highway Traffic Safety Administration (NHTSA)

