

# Part 573 Safety Recall Report

# 22V-612

**Manufacturer Name :** Kia America, Inc.**Submission Date :** AUG 10, 2022**NHTSA Recall No. :** 22V-612**Manufacturer Recall No. :** SC246**Manufacturer Information :**

Manufacturer Name : Kia America, Inc.

Address : 111 Peters Canyon Road  
Irvine CA 92606

Company phone : 800-333-4542

**Population :**

Number of potentially involved : 28,065

Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2016-2016 KIA Sedona

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

**Descriptive Information :** Certain 2016 model year Sedona vehicles manufactured from April 27, 2015 to June 27, 2015 (7,263 units).

The recall population was determined by a review of vehicle production and supplier records. The vehicles subject to this recall were not produced in VIN order.

Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or their Kia dealer.

Production Dates : APR 27, 2015 - JUN 27, 2015

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2016-2016 KIA Sorento

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

**Descriptive Information :** Certain 2016 model year Sorento vehicles manufactured from April 27, 2015 to July 9, 2015 (20,802 units).

The recall population was determined by a review of vehicle production and supplier records. The vehicles subject to this recall were not produced in VIN order.

Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or their Kia dealer.

Production Dates : APR 27, 2015 - JUL 09, 2015

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

**Description of Defect :**

Description of the Defect : The automatic transmission shift lever assembly contains a shift lock lever and holder. Some shift lock holder components may have been produced out of specification by the supplier. As a result, the shift lock lever may not return to the locked position and the shift lever can be moved out of Park and into any gear position without pressing the brake pedal, regardless of whether the ignition is on or off. If the transmission gear shifter is moved out of the Park position without pressing the brake pedal and the parking brake is not used, a vehicle rollaway can occur thereby increasing the risk of crash and injury.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A vehicle rollaway increases the risk of crash and injury.

Description of the Cause : Shift lock holder components may have been manufactured out of specification by the supplier.

Identification of Any Warning that can Occur : None

**Involved Components :**

Component Name 1 : LEVER ASSY-ATM

Component Description : AUTOMATIC TRANSMISSION SHIFT LEVER ASSEMBLY

Component Part Number : 46700-A9100 (Sedona)

Component Name 2 : LEVER ASSY-ATM

Component Description : AUTOMATIC TRANSMISSION SHIFT LEVER ASSEMBLY

Component Part Number : 46700-C5130 (Sorento)

**Supplier Identification :****Component Manufacturer**

Name : Dong Won

Address : 47, Beomjigi 141beon-gil, Danwon-gu  
Ansan-si, Gyeonggi-do Foreign States 15434

Country : Korea, Republic of

**Chronology :**

See attached document titled "2016MY Sedona and Sorento Automatic Transmission Shift Lever Assembly Chronology"

**Description of Remedy :**

**Description of Remedy Program :** All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Kia dealer. Dealers will inspect the automatic transmission shift lever assembly and if necessary, will replace the shift lock lever and holder. Kia will reimburse owners for repair expenses already incurred pursuant to Kia's General Reimbursement Plan filed May 10, 2022.

**How Remedy Component Differs from Recalled Component :** The remedy shift lock lever and holder are manufactured with the proper dimensional specification.

**Identify How/When Recall Condition was Corrected in Production :** The recall condition was corrected in production by the supplier on 6/10/2015. 2016 model year Sedona vehicles manufactured beginning on 6/28/2015 and 2016 model year Sorento vehicles manufactured beginning on 7/10/2015 were equipped with a corrected shift lock lever and holder.

**Recall Schedule :**

**Description of Recall Schedule :** The dealer notice is scheduled to begin and end on October 3, 2022, and the owner notice is scheduled to begin and end on October 7, 2022.

**Planned Dealer Notification Date :** OCT 03, 2022 - OCT 03, 2022

**Planned Owner Notification Date :** OCT 07, 2022 - OCT 07, 2022

\* NR - Not Reported