TECHNICAL INSTRUCTIONS


FOR

SAFETY (NONCOMPLIANCE) RECALL 22LA03 TIRE PRESSURE INFORMATION LABEL REPLACEMENT CERTAIN 2020 – 2022 MODEL YEAR RC F

The repair quality of covered vehicles is extremely important to Lexus. All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning Course "Safety Recall and Service Campaign Essentials" to ensure that all vehicles have the repair performed correctly.

I. OPERATION FLOW CHART

The flow chart is for reference only. *DO NOT* use it in place of the full technical instructions. Follow ALL steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



II. IDENTIFICATION OF AFFECTED VEHICLES

- 1. CHECK VEHICLE FOR CAMPAIGN ELIGIBILITY
 - a) Compare the vehicles VIN to the VIN listed on the Repair Order to ensure they match.
 - b) Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Campaign, and that it has not already been completed.

HINT:

TMNA warranty will not reimburse dealers for repairs completed on vehicles that are not affected or were previously completed, even by another dealer.

III. PREPARATION


A. PARTS

Part Number	Part Description	Quantity
42661-24560	Tire Pressure Information Label	1

IV. WORK PROCEDURE TABLE OF CONTENTS

TIRE PRESSURE INFORMATION LABEL REPLACEMENT	·· SECTION V
APPENDIX	SECTION VI

V. BACKGROUND



VI. TIRE PRESSURE INFORMATION LABEL REPLACEMENT




1. REMOVE TIRE PRESSURE INFORMATION LABEL

a) Using your fingers, remove the existing label from the vehicle.



b) After removal, degrease and clean the vehicle surface thoroughly.



2. APPLY THE **NEW** TIRE PRESSURE INFORMATION LABEL

 Temporarily place the NEW tire pressure information label as shown in the illustration and hold the label in position by hand so it doesn't move.

NOTICE:

DO NOT remove the release paper in this step.

Correct Label Position:

- Leave about 10 mm between the edge of the NEW label and the bottom edge of the existing certification label.
- Make sure that no part of the NEW label is hanging over the edges of the pillar (the entirety NEW label must be on the flat area).
- The tire icon of the NEW label is facing toward the bottom of the vehicle.



b) Remove the release paper from the upper side of the **NEW** label as shown in the illustration, and apply the label.

NOTICE:

Be careful not to touch the sticky surface of the label.



c) Remove the release paper from the lower side of the label and apply the label.



d) Firmly press the label with your hand.

NOTICE:

Especially press firmly on the label boundaries in order to prevent the label edge from peeling off.

◄ VERIFY REPAIR QUALITY ▶


If you have any questions regarding this Safety (Noncompliance) Recall, please contact your regional representative.

VII. APPENDIX

A. PARTS DISPOSAL

In accordance with Federal Regulations, please make sure all recalled parts (original parts) removed from the vehicle are disposed of in a manner in which they will not be reused, *unless* requested for parts recovery return.

B. CAMPAIGN DESIGNATION DECODER



Examples:

19LA01 = Launched in 2019, Lexus, Safety Recall Remedy Phase, 1st Safety Recall Launched in 2019

20LC02 = Launched in 2020, Special Service Campaign, 2nd Special Service Campaign Launched in 2020

21LE05 = Launched in 2021, Customer Support Program, 5th Customer Support Program Launched in 2021