

IMPORTANT SAFETY RECALL INFORMATION

Issued in Accordance
With Federal Law



URGENT SAFETY RECALL NOTICE

Your 2022 RAM 3500 LONGHORN CREW CAB 4X4 is under recall for Powertrain Control Module.

To schedule your recall repair contact your dealership or the FCA US Recall Team at [1-800-853-1403](tel:1-800-853-1403).

Recall notice issued to:



Vehicle information:

VIN



2022 RAM 3500 LONGHORN CREW CAB 4X4

Recall information: Z87/NHTSA 22V-642

Visit recalls.mopar.com for more information or call the FCA US Recall Team at [1-800-853-1403](tel:1-800-853-1403)

Details of the Recall

Your vehicle may have been built with a Powertrain Control Module (PCM) with a misaligned capacitor which could create a short to ground and cause an internal PCM loss of communication. An internal loss of communication could result in a loss of motive power, which can cause a vehicle crash without prior warning.

FCA US will repair your vehicle free of charge (parts and labor). To do this, your dealer will replace and reprogram the Powertrain Control Module. The estimated repair time is about 45 minutes. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience.

How do I schedule my **FREE** repair?

- ◆ Simply contact your Chrysler, Jeep®, Dodge or RAM dealer right away to schedule a service appointment.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations

FCA US LLC Team

1-800-853-1403

recalls.mopar.com