

Part 573 Safety Recall Report

22V-659

Manufacturer Name : Jayco, Inc.**Submission Date :** AUG 31, 2022**NHTSA Recall No. :** 22V-659**Manufacturer Recall No. :** 9901579**Manufacturer Information :****Population :**

Manufacturer Name : Jayco, Inc.

Number of potentially involved : 45

Address : 903 South Main Street

Estimated percentage with defect : 100 %

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Vehicle Information :

Vehicle 1 : 2022-2023 Jayco White Hawk

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Jayco determined the scope from its production records.

Production Dates : JUN 06, 2022 - JUL 29, 2022

VIN Range 1 : Begin : 1UJB0BP5N14N0065 End : 1UJBK0BP4P14N0073 ☒ Not sequential**Description of Defect :**

Description of the Defect : Refrigerator LP Gas line was concealed inside the underbelly.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If there is a leak in a LP gas line that is concealed it could allow gas to build up increasing the risk of a fire.

Description of the Cause : Manufacturing improperly routed the refrigerator LP gas line.

Identification of Any Warning that can Occur : Odor of LP gas.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On August 9, 2022, production reported to the codes and standards team that we built units with the refrigerator LP Line concealed in the underbelly. August 10, 2022, Codes and standards team emailed the Jayco compliance team the incident with the affected units from our production records. On August 15, 2022, this incident was discussed at WIRC (Warranty & Incident Review Committee) and elevated to CPAC (Corrective and Preventative Action Committee). On August 17, 2022, this incident was discussed at CPAC and elevated to SSC (Safety Steering Committee). On August 25, 2022, SSC discussed this incident and voted to proceed with a recall. Jayco has received no warranty claims for this situation.

Description of Remedy :

Description of Remedy Program : Reroute the refrigerator LP gas line underneath the unit underbelly so it is accessible. Repairs made prior to the recall will be handled in accordance with our General Reimbursement Plan on file with NHTSA. Jayco will file recall completion reports with NHTSA.

How Remedy Component Differs from Recalled Component : Refrigerator LP gas line will be accessible and not concealed inside the underbelly.

Identify How/When Recall Condition was Corrected in Production : August 9, 2022 all units affected on premises were placed on hold and repaired with the recall remedy.

Recall Schedule :

Description of Recall Schedule : Jayco Inc. will notify affected dealers and retail owners.

Planned Dealer Notification Date : SEP 30, 2022 - SEP 30, 2022

Planned Owner Notification Date : SEP 30, 2022 - SEP 30, 2022

* NR - Not Reported