## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

22V-681

Manufacturer Name: Daimler Trucks North America, LLC NHTSA Recall No. / MFR Recall No.: 22V-681 /FL952 Recall Subject: Improperly Installed Steering Shaft Bolt Owner Notification Beginning Date: OCT 11, 2022

**Owner Notification End Date:** OCT 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 24, 2023	2023-1	200	102	0	0
1	JAN 28, 2023	2022-4	200	65	0	0

This Document Last Updated: APR 28, 2023

## **Definitions:**

 $Report\ Quarter:\ The\ quarter\ the\ manufacturer\ is\ reporting\ recall\ completion\ figures\ (e.g.\ 2012-3\ means\ the\ 3^{\bf rd}\ quarter\ of\ 2012).$ 

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.