TOPIC	TYPE	RECALL CODE	QUESTION	ANSW	ANSWER			
				Country	Beginning Model Year	Ending Model Year	Vehicle	
				USA	2022	2023	GOLF GTI	
Safety	Safety	1000	What vehicles are included in Safety	USA	2022	2023	GOLF R	
Recall 19Q8	Recall	19Q8	What is the safety concern for Safety Recall 19Q8?  Are there any precautions I should take because my vehicle is part of Safety Recall 19Q8?	During vehicle production, the radiator may not have been affixed correctly to the intercooler. This can result in the radiator becoming loose and causing a coolant hose to contact the V-belt pulley. A coolant hose that contacts the V-belt pulley can become damaged, potentially resulting in a coolant leak. A large amount of coolant leaking onto the roadway may increase the risk of a crash for the following traffic. If the red warning light in the instrument cluster is ignored and the vehicle continues to be driven without coolant, the engine may overheat, potentially leading to a vehicle fire.  If a low coolant level is detected, the driver will see a red warning light in the instrument cluster. Customers with vehicles experiencing this condition are advised to contact an authorized Volkswagen dealer without delay to have the vehicle inspected.				
			What is the repair for the Safety Recall 19Q8?  When will the repair for Safety Recall 19Q8 be available?	authori inspect the rad interco found, V-belt v damag will be Repairs Please Volksw schedu	zed Vot the afficiator is oler. If the coowill be end is four replaces for the contact agen outle this ointme	elkswag fected v correct a loose blant ho checke und, the ed. is recal is recal tyour lealer v recall r	ntial issue, your gen dealer will vehicles to see if tly affixed to the econnection is ose and the poly d for damage. If e damaged parts I have begun. authorized without delay to epair. To set up he, please visit dealer.	