

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6309
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 12, 2022

Subject: REVISION: N222377890-01 - Safety Recall
Seat Height-Adjust Pivot Bolt May Be Loose
Customer Letter Added AND Revised Service Procedure

Models: 2022 – 2023 Chevrolet Equinox
2022 GMC Terrain

To: All General Motors Dealers

This bulletin has an updated service procedure, and the customer letter has been added. Please discard all previous copies of bulletin N222377890.

Customer Letter Mailing

The customer letter mailing will begin on October 26, 2022.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS