

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: BMW Recall 22V-xxx: Front Lamps
Date: Thursday, September 22, 2022 12:22:43 PM

Publish Date: September 22, 2022
From: Technical Service
Expiration Date: October 6, 2022

DCSnet Message
Urgent



Subject: **BMW Recall 22V-xxx: Front Lamps**




BMW AG is conducting a Voluntary Non-Compliance Recall (effective September 22, 2022) on certain Model Year 2023 BMW X7 SAV vehicles that were produced between March 9, 2022 and September 20, 2022.

Due to an electronic control unit (ECU) programming issue, potentially affected vehicles may not meet a Federal Requirement regarding the interaction between the turn signals and the day time running lamps. The ECU will be reprogrammed. Software is expected to be available later in October.

The Recall Notice and Q&A have been attached for further information.

The bulletin will be updated when additional information becomes available.

Sincerely,
Technical Service

Attachments:  [B630522 Recall Notice\[1663862994924\].pdf](#) 
 [B630522\[1663862994924\].pdf](#) 
 [B630522_22V-xyz-FAQ-\(22Sep2022\)\[1663862994924\].pdf](#)  [B630522 Recall Notice\[1663862994924\].pdf](#)
[B630522\[1663862994924\].pdf](#)
[B630522_22V-xyz-FAQ-\(22Sep2022\)\[1663862994924\].pdf](#)

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel
BMW SAV (Light Trucks), All Offering, All Region, All Areas, All Departments, All Personnel
BMW Passenger Cars, CC-All



SIB 63 05 22

2022-09-22

Recall 22V-xxx: Front Lamps

MODEL

E-Series	Model Description	Production Date
G07	X7 Sports Activity Vehicle	March 9, 2022 – September 20, 2022

AFFECTED VEHICLES

Vehicles which require this Recall Campaign to be completed will show it as “Open” when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

SITUATION

BMW AG is conducting a Voluntary Non-Compliance Recall (effective September 22, 2022) on certain Model Year 2023 BMW X7 SAV vehicles that were produced between March 9, 2022 and September 20, 2022.

Due to an electronic control unit (ECU) programming issue, potentially affected vehicles may not meet a Federal Requirement regarding the interaction between the turn signals and the day time running lamps. The ECU will be reprogrammed. Software is expected to be available later in October.

The Recall Notice and Q&A have been attached for further information.

The bulletin will be updated when additional information becomes available.

Supporting Materials

[picture_as_pdf B630522_22V-xyz-FAQ-\(22Sep2022\).pdf](#)

[picture_as_pdf B630522 Recall Notice.pdf](#)

NON-COMPLIANCE RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 22V-xxx: Front Lamps – B63 05 22

BMW AG is conducting a Voluntary Non-Compliance Recall (effective September 22, 2022) on certain Model Year 2023 BMW X7 SAV vehicles that were produced between March 9, 2022 and September 20, 2022.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

Non-Compliance Recall
22V-xyz
Front Lamps
Model Year 2023
BMW X7 SAV
Issue Date: 09/22/2022

- Q1. Which BMW Group models in the US are potentially affected by this Non-Compliance Recall?**
Model Year 2023 BMW X7 SAV models in the US are potentially affected.
- Q2. What is the specific issue?**
Due to an electronic control unit (ECU) programming issue, potentially affected vehicles may not meet a Federal Requirement regarding the interaction between the turn signals and the day time running lamps.
- Q3. Why are other models / vehicles not included in this Non-Compliance Recall?**
Other models have appropriate ECU programming.
- Q4. Can I continue to drive my vehicle?**
Yes. However, when you are notified by BMW of this Non-Compliance Recall, please contact an authorized BMW center to schedule an appointment as soon as possible. For the latest updates to this Non-Compliance Recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall). **If you are not the only driver of this vehicle, please advise all other drivers of this important information.**
- Q5. How did BMW Group become aware of the issue?**
BMW Group became aware of the issue through its quality control procedures.
- Q6. How will I be informed of this Non-Compliance Recall?**
Owners of potentially affected vehicles will be notified via First Class mail and requested to schedule an appointment with an authorized BMW center to have the remedy performed. Owners can locate their nearest authorized BMW center at [bmwusa.com/dealer](https://www.bmwusa.com/dealer).
- To ensure BMW has your recent contact and vehicle information, owners should visit [bmwusa.com/recall](https://www.bmwusa.com/recall) and click on “**Manage recall notices and contact information**”.
- Q7. How will my vehicle be remedied?**
The ECU will be reprogrammed for free and will take approximately one hour.
- Q8. Do I have to wait for BMW to contact me to have the remedy performed?**
Yes. We are in the process of implementing this Safety Recall to ensure that the necessary parts, tools, and procedures are available. For the latest updates to this recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall).