

**ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager**  
Freightliner Dealers – U.S. and Canada  
Western Star and Sterling Dealers – U.S. and Canada  
FCCC Dealers – U.S. and Canada  
Thomas Built Buses Dealers – U.S. and Canada  
Direct Warranty Customers – U.S. and Canada  
Detroit Diesel Distributors  
Export Distributors

Daimler Truck North America LLC

**WARRANTY CAMPAIGNS DEPARTMENT**  
P.O. Box 4090 800-547-0712  
Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAPortal](#)

---

REF #: ICI23-025  
Effective: 06/27/2023  
Release: 06/27/2023

**SUBJECT: FL957 – Revised Bulletin**

---

This letter is to inform you that a revised bulletin for Recall FL957 Thomas Built Bus Roof Sheet Joint is available on DTNAPortal. Please print and use the revised bulletin for all work under FL957 from this point forward.

**REVISION:** The parts and labor tables have been updated.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC link on DTNAPortal.

---

REF #: ICI23-025  
En vigueur: 27/06/2023  
Date de sortie: 27/06/2023

**OBJET: FL957 – Bulletin révisé**

---

Cette lettre a pour but de vous informer qu'un bulletin révisé pour le rappel FL957 Thomas Built Bus Roof Sheet Joint est disponible sur DTNAPortal. Veuillez imprimer et utiliser le bulletin révisé pour tous les travaux sous FL957 à partir de maintenant.

**RÉVISION:** Les tableaux pièces et main d'oeuvre ont été mis à jour.

Si vous avez des questions ou avez besoin de plus amples informations, contactez le service des campagnes de garantie en soumettant une demande via le lien WSC sur DTNAPortal.

*The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.*