



RECALL R22CD

INCORRECT HANDRAIL DIAMETER

Models Affected: It has been determined that certain Model Year 2023 Blue Bird All American (T3FE) and Vision (BBCV) Non-School Buses calling for Handrail Part Number 10075076 may have an incorrectly sized diameter.

Issue: The stepwell grab rail is 1” and needs to be 1.25”.

Corrective Action: Remove and replace grabrail.

WARNING: Always follow all Federal, State, Local and Shop safety standards and use proper safety equipment, and thoroughly read and understand all instructions before performing these procedures. Park bus on level surface, apply parking brake, turn off ignition key, and chock wheels.

Parts/Items Needed:

Item	Part Number	Description	Quantity
1	10079562	HANDRAIL ASSY,ENT DR,27.32 STANCHIONS	1

Instructions:

Step 1: Remove grab rail

Step 2: Install grab rail

