

U.S. Department of Transportation

# National Highway Traffic Safety Administration

October 27, 2022

Mr. Wesley Chestnut Shyft Group 41280 Bridge Street Novi, MI 48375 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR 22V-789

Subject: Front and Rear Suspension Fasteners Can Break

Dear Mr. Chestnut:

This letter serves to acknowledge Shyft Group's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

## Makes/Models/Model Years:

SPARTAN/K2/2023

Mfr's Report Date: October 20, 2022

NHTSA Campaign Number: 22V-789

### **Components:**

SUSPENSION: CRITICAL FASTENERS

Potential Number of Units Affected: 4

# **Problem Description:**

Shyft Group is recalling certain 2023 Spartan K2 RV chassis. The fasteners attaching the front and rear suspension to the chassis frame may have insufficient strength.

# **Consequence:**

The fasteners can break, allowing the suspension to shift and increasing the risk of a crash.

## Remedy:

Shyft Group will replace the fasteners, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Shyft Group customer service at 1-800-582-3454.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Shyft Group's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

