

22V-820
Model Year 2023
BMW X5 SAV, X7 SAV
Windshield Seal
In-Car / In-App Communication – Safety Recall Reminder
12 Sep 2023

Title:

BMW Safety Recall 22V-820: Windshield Seal

Text:

The windshield may not have been properly sealed to the vehicle during assembly. Over time, water could enter the vehicle interior and, in certain conditions, contact the power distribution box and/or an electronic control unit. In rare cases, this could lead to a short-circuit. If a short-circuit occurred, this could lead to a thermal event and increase the risk of injury.

Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.

Advise all drivers of this important information.

For the latest updates to this recall, please visit bmwusa.com/recall.

Short Text:

Important Safety Recall 22V-820: Windshield Seal. Contact an authorized BMW center immediately to get your vehicle repaired for FREE. For updates to this recall, please visit bmwusa.com/recall. Dealer locator: bmwusa.com/dealer.

Pop-Up:

Important Safety Recall: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.