

DATE: December 2022

TO: Micro Bird Distributors

SUBJECT: Recall 22-098-RUS /NHTSA # 22V826

FROM: Marie Claude Gagnon, Product Certification and Specification Specialist, Micro Bird Inc.

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Micro Bird has decided that a defect which relates to motor vehicle safety exists in certain 2021-2023 G5, 2022-2023 MBII and 2022 T-Series school buses.

In certain vehicles, the seat-level rub rails may have been attached incorrectly to the side of the bus, not offering a solid anchoring to the vertical structure members of the bus.

If the seat-level rub rail is not attached correctly, the protection against impact it offers to the passengers may be diminished, increasing the risks of injuries in case of an impact.

To complete this recall, owners will contact you to make an appointment for repair.

We request that you apply for reimbursement via the GOLs claim system with detailed invoices and list of repaired vehicles so we can update our files.

Micro Bird Corporation will provide instructions and parts, as well as reimburse labor to mitigate this recall at no charge.

The allotted time to inspect and, if needed, correct the defect is 20 minutes (0.3 hour) per vehicle.

<u>Important</u>: We want to remind you that recalled vehicles must be corrected before you sell, lease, or deliver them; vehicles returned at the end of a lease must be corrected before they can be offered for sale as used vehicles.

We apologize for any inconvenience this situation may cause and we thank you for your cooperation.