

Part 573 Safety Recall Report

22V-848

Manufacturer Name : Lamborghini (Automobili Lamborghini)

Submission Date : NOV 17, 2022

NHTSA Recall No. : 22V-848

Manufacturer Recall No. : L734-R.01.22



Manufacturer Information :

Manufacturer Name : Lamborghini (Automobili Lamborghini)
Address : Via Modena 12
Sant'Agata Bolognese (BO) 40019 -
Italy 00 99999
Company phone : 999

Population :

Number of potentially involved : 9
Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Automobili Lamborghini Countach

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : The recall population was determined through production records. Vehicles not affected by the recall have correct rear bonnet glass panels bonding.

Production Dates : JUN 30, 2022 - JUL 28, 2022

VIN Range 1 : Begin : ZHWUA9ZD9NLA11359 End : ZHWUA9ZD7NLA11442 Not sequential

Description of Defect :

Description of the Defect : Incorrect bonding of the rear bonnet glass panels may lead to adhesion issue that could result in a detachment.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The rear bonnet glass panels could fully detach from the vehicle, creating a road hazard and increasing the safety-risk of a crash for following traffic.

Description of the Cause : The defect was caused by an error in supplier's assembly phase concerning the bonding of the glass panel.

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Rear Bonnet Glass Panel

Component Description : Rear Bonnet Glass Panel

Component Part Number : 47F845155

Supplier Identification :

Component Manufacturer

Name : C.P.C. Group

Address : Via Del Tirassegno, 55
Modena 41122

Country : NR

Chronology :

Lamborghini received on October 10th 2022 one field report from Qatar market concerning a possible issue with one of the four glass panels on the rear bonnet of the model Countach MY22 through its Authorized Dealer Network. No other problem was reported from any other market.

Lamborghini started a thorough investigation involving the supplier of rear bonnet in an effort to determine a root cause.

On October 25th 2022, Lamborghini after internal analysis and testing found that the defect was caused by an error in supplier's assembly phase concerning the bonding of the glass panel. Lamborghini determined that it is not possible to exclude that other panels could fully detach from the rear bonnet, thereby potentially creating a road hazard.

The outcome of the investigation was presented to the Lamborghini Product Safety Committee on November 10th 2022 which decided unanimously to launch a proactive recall campaign worldwide. Lamborghini has not received any reports of a crash or injury due to this topic.

Description of Remedy :

Description of Remedy Program : Affected vehicles will be inspected for appropriate bonding of the glass panels and, if necessary, they will be replaced. Lamborghini will not offer a reimbursement plan under this recall as all affected vehicles are still under warranty.

How Remedy Component Differs from Recalled Component : In case a replacement is necessary, the spare glass panel installation will be carried out according to manufacturer specification.

Identify How/When Recall Condition was Corrected in Production : Vehicles produced from mid October 2022 have been inspected for proper bonding of rear bonnet glass panels and the assembly process was assessed and revised in order to prevent unknown variables.

Recall Schedule :

Description of Recall Schedule : Customers will be notified by registered mail and customer app; while dealers through Lamborghini dealer portal.
Planned Dealer Notification Date : JAN 09, 2023 - JAN 09, 2023
Planned Owner Notification Date : JAN 13, 2023 - JAN 13, 2023

* NR - Not Reported