



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 6, 2022

Ms. Briana Green
Senior Corporate Counsel
Xos, Inc.
3550 Tyburn St.
Los Angeles, CA 90065

NEF-107MR
22V-881

Subject: Brake Lines Improperly Routed

Dear Ms. Green:

This letter serves to acknowledge Xos, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

XOS/RM01/2021
XOS/SA01/2021
XOS/SV05/2021-2022

Mfr's Report Date: November 29, 2022

NHTSA Campaign Number: 22V-881

Components:

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:HOSES, LINES/PIPING, AND FITTINGS

Potential Number of Units Affected: 260

Problem Description:

Xos, Inc. (Xos) is recalling certain 2021 RM01, SA01 and 2021-2022 SV05 vehicles. The brake lines may be the incorrect length and incorrectly routed, which can result in a brake fluid leak.

Consequence:

A brake fluid leak can lead to an increase in stopping distance, increasing the risk of a crash.

Remedy:

Dealers will replace the brake lines, free of charge. Owner notification letters are expected to be mailed on December 14, 2022. Owners can contact Xos' customer service at 989-289-6765.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to www.nhtsa.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Xos, Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement