

# Part 573 Safety Recall Report

# 22V-897

**Manufacturer Name :** Porsche Cars North America, Inc.**Submission Date :** DEC 06, 2022**NHTSA Recall No. :** 22V-897**Manufacturer Recall No. :** ANB7**Manufacturer Information :**

Manufacturer Name : Porsche Cars North America, Inc.

Address : One Porsche Drive

Atlanta GA 30354

Company phone : 1-800-767-7243

**Population :**

Number of potentially involved : 53

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2022-2023 Porsche 911

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles have been identified through production records.

Only certain specific vehicles equipped with a leather-covered dashboard option assembled within a defined production batch are affected.

Production Dates : SEP 13, 2022 - NOV 29, 2022

VIN Range 1 : Begin : WPOAA2A90PS205004 End : WPOCD2A93NS261161  Not sequential**Description of Defect :**

Description of the Defect : On the affected vehicles, in the event of a passenger airbag deployment, there is the possibility that the console of the dashboard may break and separate. This could impair proper front passenger air bag deployment.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Impaired front passenger air bag deployment or the potential for resulting dashboard damage during deployment could increase the risk of front passenger injury in a crash.

Description of the Cause : The adhesive used between the air bag lid and the leather dashboard cover may not meet the requirements as specified in production process.

Identification of Any Warning that can Occur : Not applicable

## Involved Components :

Component Name 1 : Leather-covered dashboard

Component Description : Leather-covered dashboard

Component Part Number : 992857003P XXX (XXX denotes the various color codes of the dashboard))

## Supplier Identification :

### Component Manufacturer

Name : Porsche AG production plant Zuffenhausen

Address : NR

Foreign States

Country : Germany

## Chronology :

In mid of October, 2022, Porsche became aware of instrument panel conformity of production test results that deviated from specification. The potential irregularity was related to a test at high test temperature.

In order to analyze possible effects of this issue on the deployment behavior of the passenger airbag and the behavior of instrument panel components, further tests were carried out in a certain temperature range.

On November 24, 2022, further test results indicated a possible influence on passenger air bag deployment. This was further analyzed.

In parallel to this, the affected production period and the resulting particular batch was identified.

On November 30, 2022, Porsche decided to recall the subject vehicles.

## Description of Remedy :

Description of Remedy Program : The dashboard will be replaced.

How Remedy Component Differs from Recalled Component : Parts assembled outside of a defined production batch are unaffected because correct adhesive was utilized during assembly.

Identify How/When Recall Condition was Corrected in Production : Parts assembled outside of a defined production batch are unaffected because correct adhesive was utilized during assembly.

**Recall Schedule :**

Description of Recall Schedule : Customers will be notified within 60 days of this report. If the remedy is not available by 60 days an interim letter will be sent.

Planned Dealer Notification Date : DEC 21, 2022 - DEC 21, 2022

Planned Owner Notification Date : FEB 03, 2023 - FEB 03, 2023

\* NR - Not Reported