

ANB7 Stop Delivery/Recall Campaign - Replacing dashboard

ANB7 Stop Delivery/Recall Campaign - Replacing dashboard

ID Number	ANB7
Models	911 (992)
Model Years	2022-2023
Number of VINs affected	48 (9 Stop Delivery)
VIN list	Attached
Issue Description	<p>The adhesive used between the air bag lid and the leather dashboard cover may not meet the requirements as specified in production process. In the event of a passenger airbag deployment, there is the possibility that the console of the dashboard may break and separate. This could impair proper front passenger air bag deployment.</p>
What Should Dealers Do?	<p>The repair is not available at this time.</p> <p>Please do not deliver the subject Stop Delivery vehicles until the remedy is complete.</p>
What will Porsche Do?	<p>Vehicles will have the remedy performed once it is available.</p>
TI Number	TI to be released at a later date
Customer Letter	To be posted at a later date
Customer Reactive Statement	<p>Our highest priority is the safety of our cars, and to this end we regularly review the quality of our work. In these reviews, a potential issue with passenger airbags was discovered in a small number of 911 cars with optional leather-covered dashboards from model years 2022 and 2023. In certain cars, the adhesive that bonds the leather dashboard cover to the passenger airbag lid may not meet specifications, which could result in the airbag deploying incorrectly. No incidents have been reported. Out of an abundance of caution, customers with an affected car may want to</p>

drive without a front passenger until the part in question is replaced.

Customers will be promptly notified so that Porsche dealers can install new dashboard assemblies. There will be no charge for this.

Important information

IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.