

U.S. Department of Transportation

# National Highway Traffic Safety Administration

December 13, 2022

Ms. Robin Grangruth Legal Specialist KTM North America, Inc. 38429 Innovation Ct Murrieta, CA 92563

1200 New Jersey Avenue SE Washington, DC 20590

NEF-107ES 22V-900

**Subject:** Wiring Harness Damage May Cause Engine Stall

Dear Ms. Grangruth:

This letter serves to acknowledge KTM North America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

#### Makes/Models/Model Years:

KTM/1290 SUPER DUKE R/2020-2022

Mfr's Report Date: December 6, 2022

NHTSA Campaign Number: 22V-900

**Components:** 

ELECTRICAL SYSTEM: WIRING

**Potential Number of Units Affected:** 1,040

### **Problem Description:**

KTM North America, Inc. (KTM) is recalling all 2020-2022 1290 Super Duke R and Super Duke R EVO motorcycles. The main wiring harness may be misrouted or missing parts, which can cause wiring harness damage and result in an electrical short-circuit or engine stall.

## **Consequence:**

An engine stall can increase the risk of a crash.

# Remedy:

Dealers will inspect and repair the main wiring harness installation, as necessary, free of charge. Owner notification letters are expected to be mailed January 26, 2023. Owners may contact KTM customer service at 1-888-985-6090. KTM's number for this recall is KTB2211.

# Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



# Please ensure the following requirements are met:

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

We have received KTM's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

KTM North America, Inc.'s contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

