The information contained in this report was submitted pursuant to 49 CFR §573

NR

Part 573 Safety Recall Report

Manufacturer Name :Adventurer LPSubmission Date :JAN 11, 2023NHTSA Recall No. :23E-001Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name :Adventurer LPAddress :3303 West Washington Ave.
Yakima WA 98903Company phone :509-895-7064

Equipment Information :

Brand / Trade 1:	Adventurer LP
Model :	Adventurer 19RD, Adventurer 23RB, Adventurer 24DS
Part No. :	RegO 901C3, 901C5
Size :	NR
Function :	NR
Descriptive Information :	Per Vendor Notice: RegO has become aware of a potential issue with the female POL threads on a limited number of RegO model 901C3 and model 901C5 service valves. In some instances, the thread depth of the POL outlet is less than specification, which could result in a leak of propane. Potentially affected valves would have been installed in a limited number of Manchester Tank branded RV tanks dated 2021 and 2022. Once we were told about the issue, we were able to generate a list of potential affected units based on purchases of suspect tanks during the time period the vendor provided.
	The units that were identified are part of a single dealer rentail fleet.
Production Dates :	MAR 04, 2021 - MAY 27, 2022



Number of potentially involved : 263

Estimated percentage with defect :

Population :

23E-001

Page 2

Description of Defect :

Description of the Defect :	PER VENDOR NOTICE: RegO has become aware of a potential issue with the female POL threads on a limited number of RegO model 901C3 and model 901C5 service valves. In some instances, the thread depth of the POL outlet is less than specification, which could result in a leak of propane. Potentially affected valves would have been installed in a limited number of Manchester Tank branded RV tanks dated 2021 and 2022. THIS COULD RESULT IN A FIRE OR EXPLOSION AND
	SERIOUS PERSONAL INJURY, PROPERTY DAMAGE, OR BOTH.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	PER VENDOR NOTICE: RegO has become aware of a potential issue with the female POL threads on a limited number of RegO model 901C3 and model 901C5 service valves. In some instances, the thread depth of the POL outlet is less than specification, which could result in a leak of propane. Potentially affected valves would have been installed in a limited number of Manchester Tank branded RV tanks
	dated 2021 and 2022. THIS COULD RESULT IN A FIRE OR EXPLOSION AND SERIOUS PERSONAL INJURY, PROPERTY DAMAGE, OR BOTH.
Description of the Cause :	No cause provided by vendor at time of notice.
•	
Identification of Any Warning that can Occur :	NR

Involved Components :

Component Name :Service ValveComponent Description :NRComponent Part Number :901C3 and 901C5

Supplier Identification :

Component Manufacturer

Name : RegO Address : 100 RegO Drive

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Elon North Carolina 27244 Country : United States

Chronology :

Adventurer MFG was notified of the safety issue on June 19 2022. We sent the potential affected unit information to our dealer customer on 10-17-2022.

Description of Remedy :

Description of Remedy Program :	See attached vendor notice.
How Remedy Component Differs from Recalled Component :	See attached vendor notice.
	When we were notified of the safety issue our engineering and quality control team completed 100% inspection of installed and non installed components on our site. All of the parts inspected were in the "good part" condition based on the field service parameters provided by the vendor.

Recall Schedule :

Description of Recall Schedule :	We already notified our dealer of the potential affected unit list so they can coordinate inspection of the units in their unit fleet.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR Address : NR NR Country : NR Company Phone : NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573

23E-001