



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

February 8, 2023

Mark Rubalcaba  
Harbor Freight Tools  
26677 Agoura Road  
Calabasas, CA 91302

NEF-107KL  
23E-006

**Subject:** Over-pressurized Fluid Dispenser Lid May Detach

Dear Mark Rubalcaba:

This letter serves to acknowledge Harbor Freight Tools's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

HOLT INDUSTRIES/EXTRACTOR AND DISPENSER/9999

**Mfr's Report Date:** February 3, 2023

**NHTSA Campaign Number:** 23E-006

**Components:**

EQUIPMENT

**Potential Number of Units Affected:** 34,570

**Problem Description:**

Harbor Freight Tools (Harbor Freight) is recalling certain Holt Industries Deluxe Manual Fluid Extractor and Dispenser units with part number 56384. When the unit is in dispense mode, the pressure relief plug may fail and result in a build-up of excessive pressure.

**Consequence:**

Excessive pressure can cause the lid to suddenly detach, increasing the risk of injury.

**Remedy:**

Harbor Freight will provide a replacement lid ring and pour spout cap with an integrated pressure relief valve, along with instructions, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Harbor Freight customer service at 1-800-444-3353.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers.



Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

**Please ensure the following requirements are met:**

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

**AMENDED 573 REQUIRED.**

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

**AMENDED 573 REQUIRED.**

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

Harbor Freight Tools's contact for this recall will be Kristin Lepper who may be reached by email at [kristin.lepper@dot.gov](mailto:kristin.lepper@dot.gov). We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is written in a cursive style with a checkmark at the end.

Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement