



IMPORTANT SAFETY RECALL!

Harley-Davidson Announces Recall of Certain Accessory Softail Shock Kits (Recall 0182)

This recall involves the following Harley-Davidson Parts & Accessories (P&A) components:



**Tall Rear Shock
(P/N 54000294)**



**Profile Low Rear Suspension
(P/N 54000134)**

- What is the Issue?** The fastener that retains the rear shock absorber adjuster on your motorcycle may fracture, potentially allowing the rear shock absorber adjuster to contact the rear tire. A risk of a crash exists if contact between the rear shock absorber adjuster and tire remains undetected, resulting in a loss of pressure.
- Date Range** These kits were sold as accessories for certain Model Year 2018 through 2023 Softail models and shipped to Harley-Davidson dealers between March 1st, 2018 and August 22nd, 2023.
- Kit Fitments** Tall Rear Shock (P/N 54000294):
Fits '18-later Softail® models (except FXFB, FXFBS, FLFB and FLFBS).

Profile Low Rear Suspension (P/N 54000134):
Fits '18-later FLHC and FLHCS models.
- What Should You Do?** Please contact your authorized Harley-Davidson motorcycle dealer and arrange an appointment to have your motorcycle repaired.
- Questions?** If you have questions concerning this recall, please contact Harley-Davidson Motor Company, Inc. at 1-800-258-2464 in the U.S. or 1-414-343-4056 world-wide.

(Post until September 1st, 2024)