

# SAFETY RECALL NOTICE 605 - SPEED TRIPLE 1200 RS & RR

## ADDITION OF FAN ASSEMBLY HEAT SHIELD

### Notice Information

Ref	23388
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

**TOL NOTICE (US&CA) – January 31, 2023**

**TOL Ref. #23388-SVC**

### SAFETY RECALL NOTICE 605 - SPEED TRIPLE 1200 RS & RR ADDITION OF FAN ASSEMBLY HEAT SHIELD

Triumph Motorcycles has initiated a voluntary safety recall affecting a specific VIN range of the above-referenced model. We require your immediate attention to rectify the below machines.

Model Code	Model	Model Year
PB1	Speed Triple RS	2022 & 2023
PJ1	Speed Triple RR	2022 & 2023
<b>VIN RANGE: AD2117 to BJ9267 (All Markets except Brazil)</b>		

#### **WHAT IS THE PROBLEM?**

The radiator fan may malfunction due to overheating caused by high ambient temperature and slow-moving traffic conditions. Coolant may be displaced if the rider ignores the instrument warning light and continues to operate the motorcycle at low-speed, which increases the risk of an injury.

#### **WHAT WILL TRIUMPH DO?**

To address this condition, Triumph is launching a new recall as described in the above Safety Recall Action Notice.

All arrangements for updating of our computer systems have been completed.

Notification letters to current customers will be mailed on or shortly after February 1, 2023, explaining the action and advising them to return their bike to a Triumph dealer to have the modification carried out free of charge.

The bulletin instructs that affected VINS will require an additional Heat shield fitted to the fan assembly.

### **WHAT SHOULD YOU DO?**

All affected motorcycles are to be repaired in accordance with the above Safety Recall Action Notice. Refer to the [attached instructions](#) for more information.

It is imperative that any owner who has purchased an affected machine be contacted by you immediately and asked to return the machine for modification.

### **TRIUMPH DEALERS SHOULD TAKE THE FOLLOWING ACTIONS:**

1. Quarantine all unsold motorcycle stock (including motorcycle stock for sale on your website and with 3rd parties) and make arrangements to repair as per the above Safety Recall Action Notice prior to any further deliveries to customers.
2. Owners of machines outside of the affected VIN range are not connected with this action and may therefore require reassurance.
3. Using your own records please contact affected customers to arrange repairs at the earliest convenient opportunity.
4. This action is likely to increase visitor traffic to your showroom and service areas. Please ensure all arrangements are made to best accommodate them.

**FEDERAL LAW PROHIBITS THE DELIVERY OF A RECALLED MOTORCYCLE UNDER A SALE OR LEASE UNTIL THE REMEDY HAS BEEN PERFORMED.**

We apologize for the inconvenience this may cause, but we are taking this action in the interest of our customers' personal safety and satisfaction with our products. We thank you in advance for your anticipated cooperation.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.