

IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s) with the VIN(s) indicated on the enclosed owner response cards.

> **AUTOCAR, LLC RECALL ACX-2303** NHTSA RECALL 23V023 March 2023

Dear Autocar Truck Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 11353, 2008 - 2020 model year WXLL, WX, ACX (Xpeditor), ACTT (Xspotter) and ACMD (Xpert) chassis. The WXLL chassis were manufactured between March 12, 2007, and June 5, 2009, with non-sequential serial numbers in the range of 205511 and 209868. The WX chassis were manufactured between February 6, 2007, and October 30, 2009, with non-sequential serial numbers in the range of 205422 through 210109. The ACX chassis were manufactured between November 30, 2007, and March 10, 2020, with non-sequential serial numbers in the range of 206686 through 233162. The ACTT chassis were manufactured between January 12, 2009, and January 20, 2020, with non-sequential serial numbers in the range of 208644 through 232396. The ACMD chassis were manufactured between January 19, 2013, and February 8, 2016, with non-sequential serial numbers in the range of 215560 through 222135. Our records indicate that your vehicle was manufactured within this time and may contain the defect described herein.

Autocar Xpeditor (ACX, WX, WXLL) 2008-2020, Xspotter (ACTT) MY 2010-2020 and **MODELS**

AFFECTED: Xpert (ACMD) MY 2012-2016.

COMPONENTS The parking brake valve vent line. AFFECTED:

SAFETY DEFECTS A worn park brake control valve (PP1) can develop an internal leak and pass air through the exhaust port after the park brake is applied. Under specific conditions, the internal leak AND POTENTIAL RISKS: combined with vent line plumbing may result in accumulated back pressure sufficient to

allow the park brakes to release, increasing the risk of a crash.

REPAIR The parking brake control valve vent line will be removed at no charge. **REQUIRED:**

TIME REQUIRED The labor time to repair your vehicle is .50 hour. FOR THE REPAIR:

WHAT YOU To have your vehicle repaired, contact your local authorized Autocar service site or email SHOULD DO:

warranty@autocartruck.com.

ACF 00002 Rev. 000



PRIOR REPAIRS:

If you have previously paid for repairs relating to this recall you may be entitled to recover the amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

NOTICE REGARDING LEASED VEHICLES:

If you are a Lessor (as defined below) of a vehicle that is affected by this notice, you are obligated under federal law to provide a copy of this Notice to the lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the lessee(s) to whom you send a copy of this Notice, the date you send the Notice and the VIN of the vehicle that you have leased to the lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles, as of the date of this Notice.

OWNER RECALL RESPONSE CARD:

The enclosed Owner Recall Response Card identifies your vehicle. Please complete this postage-paid card and return it to Autocar. If you do not own, have sold or have traded the vehicle identified on the card, please indicate that on the postage-paid card and return it to Autocar.

ASSISTANCE:

If you need assistance with this recall, call our toll-free numbers below or write to Autocar at:

Autocar, LLC Service & Warranty Departments 551 S. Washington St. Hagerstown, Indiana 47346 888-218-3611 (Toll Free) 877-973-3486 (Toll Free)

You may also submit a complaint to:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Avenue SE Washington, DC 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 800-424-9153); or go to http://www.safercar.gov.

We regret any inconvenience this recall may cause, but we hope you recognize Autocar's concern for your safety and satisfaction with your vehicle.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000