

**23V-039**  
**Model Year 2023**  
**BMW 2 Series Coupe**  
**Rear Seat Side Air Bag**  
**In-Car / In-App Communication – Safety Recall Reminder**  
**21 Jun 2023**

**Title:**

BMW Safety Recall 23V-039: Side Air Bag Cover (Rear Seats)

**Text:**

The side air bag cover panel on the rear seats may not have been produced to specifications by the supplier. In certain crashes where side air bag deployment is warranted, the cover panel may break. If this happens, then the side air bag may not deploy as intended, which could increase the risk of injury.

Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: [bmwusa.com/dealer](http://bmwusa.com/dealer).

Advise all drivers of this important information.

For the latest updates to this recall, please visit [bmwusa.com/recall](http://bmwusa.com/recall).

**Short Text:**

Important Safety Recall 23V-039: Side Air Bag Cover (Rear Seats). Contact an authorized BMW center immediately to get your vehicle repaired for FREE. For updates to this recall, please visit [bmwusa.com/recall](http://bmwusa.com/recall). Dealer locator: [bmwusa.com/dealer](http://bmwusa.com/dealer).

**Pop-Up:**

Important Safety Recall: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: [bmwusa.com/dealer](http://bmwusa.com/dealer).