

# Part 573 Safety Recall Report

## 23V-053

**Manufacturer Name :** Bombardier Recreational Products, Inc.**Submission Date :** FEB 05, 2023**NHTSA Recall No. :** 23V-053**Manufacturer Recall No. :** To be provided**Manufacturer Information :****Population :****Manufacturer Name :** Bombardier Recreational Products, Inc.**Number of potentially involved :** 1,720**Address :** 726 Saint-Joseph Street**Estimated percentage with defect :** 12 %

Valcourt, Quebec 00 JOE 2LO

**Company phone :** 450-532-2211**Vehicle Information :****Vehicle 1 :** 2022-2022 Can-Am Spyder F3 and F3-S**Vehicle Type :** MOTORCYCLES**Body Style :** OTHER**Power Train :** GAS

**Descriptive Information :** This recall is related to an inadequate batch of mirror housings molded in April 2022. BRP included in the recall all vehicles which could have been equipped with mirror assemblies made with a mirror housing from this April 2022 batch. Vehicles included in the safety recall were produced from January 27 to May 27, 2022. Some mirror assemblies were not available (back order) when the vehicles were produced therefore, MY 2022 vehicles produced before April 2022 could be equipped with the involved mirror housings. Vehicles excluded from the recall had mirrors assemblies made with mirror housings from a different batch.

**Production Dates :** JAN 27, 2022 - MAY 27, 2022**VIN Range 1 : Begin :**

NR

**End :** NR☐ Not sequential**Description of Defect :****Description of the Defect :** The rearview mirror(s) may dislodge from the housing.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** This can result in an increased risk of a crash due to the decreased visibility for the driver.**Description of the Cause :** BRP found that there was a high probability that the issue was due to a wrong plastic injection control for the mirror housings by its supplier for a batch molded in April 2022.

Identification of Any Warning None  
that can Occur :

### Involved Components :

Component Name 1 : To be provided

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : Zadi

Address : Via C. Marx, 138  
CARPI (MO) Foreign States 41012

Country : Italy

### Chronology :

At the end of November 2022, BRP confirmed a trend of high warranty rates of mirror falling from the housing. While most of the mirrors were found in the bottom of the crate at dealership, BRP received reports of mirrors falling while riding representing 9% of the overall claims.

In trying to understand the trend, BRP made various tests and validations. BRP found that there was a high probability that the issue was due to a wrong plastic injection control for the mirror housings by its supplier for a batch molded in April 2022.

With all the information collected and analyzed, BRP decided on January 27, 2023 had enough information to report and wants to proceed with a safety recall.

No accident was reported worldwide.

**Description of Remedy :**

Description of Remedy Program : BRP is issuing a safety recall.  
BRP is targeting to inform dealers about this situation on February 9 and should start the mailing for consumers in the following week. The parts availability dates will be included in the communications.  
BRP has the addresses of the vehicle owners in its warranty database and will send them a notice by mail and e-mail, if available.  
BRP will instruct its dealers to install new mirror assemblies with an assembly date from January 10, 2023. The dealer is unable to see the molding date of the mirror housing once it is assembled with the mirror. The dealer can only see the date of the mirror assembly.  
As the vehicles are still under the manufacturer's warranty, there is no plan for separate reimbursement plan for customers who had this issue.

How Remedy Component Differs from Recalled Component : The mirror assemblies will have a mirror housing from a certified batch from the supplier with adequate molding parameters.

Identify How/When Recall Condition was Corrected in Production : The supplier is increasing its molding parameters control.

**Recall Schedule :**

Description of Recall Schedule : BRP is targeting to inform dealers about this situation on February 9 and should start the mailing for consumers in the following week. The parts availability dates will be included in the communications.

Planned Dealer Notification Date : FEB 09, 2023 - FEB 09, 2023

Planned Owner Notification Date : FEB 17, 2023 - FEB 24, 2023

\* NR - Not Reported