OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-061

Manufacturer Name: Forest River, Inc.
Submission Date: FEB 10, 2023
NHTSA Recall No.: 23V-061
Manufacturer Recall No.: 225-1601



Manufacturer Information:

Population:

Manufacturer Name: Forest River, Inc.

Number of potentially involved: 12

Address: 55470 CR 1

Estimated percentage with defect : 100%

P.O. Box 3030 Elkhart IN 46515-3030

Company phone: 1-800-348-7440

Vehicle Information:

Vehicle 1: 2022-2023 Forest River Inc. Coachmen Galleria Class B Recreational Vehicles

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : NR

Descriptive Information: The scope was determined using manufacturing records of when the manufacturing

plant switched to using the subject Suburban two burner cooktop.

US Model and Quantity

 2022
 GALLERIA
 GAB24AM4X4 2

 2022
 GALLERIA
 GAB24FLM4X41

 2023
 GALLERIA
 GAB24QM 1

 Total
 4

Production Dates: JUL 27, 2022 - DEC 08, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2023-2023 Forest River Inc. Coachmen Beyond Class B Recreational Vehicles

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : NR

Descriptive Information: The scope was determined using manufacturing records of when the manufacturing

plant switched to using the subject Suburban two burner cooktop.

US Model and Quantity

2023BEYONDBYB22CAWD22023BEYONDBYB22DAWD42023BEYONDBYB22RBAWD1Total7

Production Dates: JUL 27, 2022 - DEC 08, 2022

 Vehicle 3: 2023-2023 Forest River Inc. Coachmen Nova Class B Recreational Vehicles

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : NR

Descriptive Information: The scope was determined using manufacturing records of when the manufacturing

plant switched to using the subject Suburban two burner cooktop.

US Model and Quantity

2023 NOVA NAB2ORB 1 Total 1

Production Dates: JUL 27, 2022 - DEC 08, 2022

Description of Defect:

Description of the Defect: According to the Recall Notice - 23E002 - received from Suburban: "Suburban

Manufacturing has decided that a defect which relates to motor vehicle safety exists in SDS2 – 2 Burner cooktops that were installed in recreational vehicles. The internal aluminum burner tubes connecting the gas valves to the cook top

burners can fracture from excessive vibration or shock experienced in

recreational vehicles."

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: According to the Recall Notice - 23E002 - received from Suburban: "The

burner tube could crack resulting a leak of propane when the top burner gas valve is opened to use the appliance. If ignited the propane could result in a

fire and/or explosion which could result in personal injury."

Description of the Cause: Unknown

Identification of Any Warning According to the Recall Notice - 23E002 - received from Suburban: None stated

that can Occur: on the notice.

Involved Components:

Component Name 1 : 2 Bruner Cooktops
Component Description : 2 Burner Cooktops

Component Part Number: SDS2

Component Name 2: Burner Tube

Component Description: Burner Tube

Component Part Number: N/A

Supplier Identification:

Component Manufacturer

Name: Suburban Manufacturing

Address: 676 Broadway St.

Dayton Tennessee 37321

Country: United States

Chronology:

On February 7, 2023, Forest River's Office of Corporate Compliance ("OCC") was made aware of a notice of recall the manufacturing plant received from a supplier. OCC opened a research item the same day.

On February 9, 2023, Forest River's Corporate Safety Committee was informed of this Equipment Pass Through Recall

A-1 On February 10, 2023, amended the remedy instructions as per the acknowledgement letter.

Description of Remedy:

Description of Remedy Program: Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River, Coachmen or Suburban Dealer or Service Center will need to perform the remedy. A-1 According to recall 23E002, the remedy will be to install a regulator support bracket to eliminate the vibration of the burner tube.

What is the Forest River Customer Service Phone Number? (574)

825-6307

What is the Suburban Customer Service Phone Number? (423) 775-2131 Ext 7101

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:

Coachmen Class B Forest River. Inc.

Attn: WARRANTY MANAGER

PO Box 30

Middlebury, IN 46540

How Remedy Component Differs Unknown

from Recalled Component: Suburban Manufacturing

P: (423) 775-2131 676 Broadway St. Dayton, TN 37321

Affected Component Part Number SDS2

Affected Component Name & Description - 2 Burner cooktops

Affected Component Part Number N/A

Affected Component Name & Description – Burner Tube

Identify How/When Recall Condition Unknown was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Forest River has the utmost urgency in our recalls. Forest River will send

suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out

as soon as NHTSA provides any correction(s) and an Acknowledgement

Letter.

Planned Dealer Notification Date : MAR 21, 2023 - MAR 21, 2023 Planned Owner Notification Date : MAR 21, 2023 - MAR 21, 2023

* NR - Not Reported