## IMPORTANT SAFETY RECALL

March 29, 2023

GILLIG Campaign ID Number: 23V-075

This notice applies to your vehicle(s) [insert VINs]

<Name>

<Title>

<Property>

<Address>

<City>, <State> <ZIP>

Attn: <Name>

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

GILLIG has decided that a defect, which relates to motor vehicle safety, exists certain model year 2022 through 2023 Low Floor transit buses manufactured between 01/27/2022 and 02/07/2023.

## What The Issue Is:

GILLIG has determined that incorrect draglink parts may have been installed during the vehicle assembly process. The affected part numbers are #05-35402-000 and #05-35402-004. An incorrect draglink match may potentially result in long-term damage of the steering system, affect vehicle controllability and increase the risk of a crash.

As a result of the above, GILLIG has decided to voluntarily initiate a safety recall campaign for the vehicle population that may be affected by the issue.

## What We Are Asking You To Do:

- 1. We are asking you to follow a procedure to inspect and, when necessary, replace and/or re-torque all the affected parts.
- 2. After the completion of the procedure, return the VIN sheet stating that the recall service has been completed.

## What GILLIG Will Do For You:

- 1. GILLIG will provide a procedure with clear instructions on how to perform the inspection and, when necessary, the replacement and/or re-torque of all affected parts to the manufacturer specifications
- 2. When needed, GILLIG will supply all necessary replacement parts.
- 3. GILLIG will pay a reasonable warranty claim for performing this function. GILLIG estimates a maximum time of 30 min. per vehicle required to perform this function.

GILLIG Campaign ID Number: 23V-075

March 29, 2023

Page 2

Any questions regarding the information should be directed to GILLIG Service at <u>field-service@GILLIG.com</u>.

If after having attempted to take advantage of this recall you believe you have not been able to have your bus remedied without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <a href="http://www.safercar.gov">http://www.safercar.gov</a>.

Federal regulations require that any vehicle lessor receiving the recall notice must forward a copy of this notice to the vehicle lessee within ten days.

We regret any inconvenience that this situation may cause you. GILLIG wants to assure you that we are concerned about customer safety and your continued satisfaction with our products.

Sincerely,

GILLIG, LLC

Victor Doran Executive Director, Quality & Service

CC: Mr. Greg Vismara, V.P., Engineering, GILLIG LLC
Mr. Marco Genova, Product Safety & Compliance Manager, GILLIG LLC