

23PBB – Bendix 2.1m Medium Duty Brake Pedal Plunger: NHTSA #23V087, TC #2023-070

 [Edit](#)  [Clone](#)

Number

23PBB

Supplier

Bendix

Date

2/17/2023

What's New

Safety Recall

The brake pedal plunger which connects the brake pedal to the brake valve may dislodge after the pedal is fully depressed, and rapidly released (side slip foot brake release). If the plunger in the brake pedal assembly dislodges the driver may be unable to apply the service brakes, which may increase the risk of a crash.

Interim Notification

This is to inform dealers of the existence of a safety recall. This bulletin will be updated when repair procedures are developed, and necessary parts are available.

Situation

4209 (4015 U.S. and 194 Canada) 536, 537, and 548 chassis manufactured between 6/16/2020 and 01/25/2023.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.