## **Recall Quarterly Report**

23V-088

Manufacturer Name : Suzuki Motor USA, LLC NHTSA Recall No. / MFR Recall No. : 23V-088 /2A99 Recall Subject : Incorrect Position of Master Cylinder/FMVSS 122 Owner Notification Beginning Date : MAR 01, 2023 Owner Notification End Date: JAN 12, 2024



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 19, 2024	2023-4	2,552	1,704	115	126
3	OCT 16, 2023	2023-3	2,552	1,641	255	117
2	JUL 20, 2023	2023-2	2,552	1,339	131	113
1	APR 21, 2023	2023-1	2,552	424	53	63

This Document Last Updated : JAN 24, 2024

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7