

# Part 573 Safety Recall Report

## 23V-103

**Manufacturer Name :** Aluminum Trailer Company (ATC)

**Submission Date :** MAR 16, 2023

**NHTSA Recall No. :** 23V-103

**Manufacturer Recall No. :** 23E-002



### Manufacturer Information :

**Manufacturer Name :** Aluminum Trailer Company (ATC)

**Address :** 751 N Tomahawk Trail

Nappanee IN 46650

**Company phone :** 574-773-2440

### Population :

**Number of potentially involved :** 757

**Estimated percentage with defect :** 11 %

### Vehicle Information :

**Vehicle 1 :** 2021-2023 ATC Toyhauler and Quest Trailers

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** In conjunction with recall issued by Suburban Manufacturing (22E-002), All SDS2 two burner cooktops issued to ATC during the established timeline of 1/16/18 through 1/11/23. 757 ATC toyhaulers and quest trailers that were built during that time period that use the Suburban SDS2 2 burner drop in cooktop question are impacted

**Production Dates :** DEC 16, 2020 - JAN 31, 2023

**VIN Range 1 : Begin :** 5JX1C2425MD221925 **End :** 5JX1U2428PE230663

☒ Not sequential

### Description of Defect :

**Description of the Defect :** Suburban Mfg has advised on Recall 23E-002 that certian vehicles equipped with SDS2- 2 burner drop in cooktops that were supplied during the period of 1/16/18 to 1/11/23 may have a burner tube that could crack resulting in a propane leak.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** The internal aluminum burner tube connected the gas valve may fracture from excessive vibration or shock and may crack resulting in a gas leak when the gas valve is opened to use the appliance. The resulting gas may result in a fire and/or explosion which could result in personal injury

**Description of the Cause :** The internal aluminum burner tube that connects the gas valves to the cooktop burners may fracture from excessive vibration or shock experienced through travel.

**Identification of Any Warning that can Occur :** The owner could possibly hear a louder than normal hissing sound or small propane odor when the cooktop gas valve is in the on position.

## Involved Components :

**Component Name 1 :** SDS2- 2 Burner Drop In Cooktop

**Component Description :** 2 burner drop in cooktop

**Component Part Number :** 0017890

## Supplier Identification :

### Component Manufacturer

**Name :** Suburban Manufacturing Co

**Address :** 676 Broadway  
Dayton Tennessee 37321

**Country :** United States

## Chronology :

Suburban Mfg notified of recall 22E-002. After review of the time period provided in the recall, it was determined that 757 toyhauler and quest trailers are potentially impacted by the recall.

## Description of Remedy :

**Description of Remedy Program :** ATC will supply replacement materials if needed as they will be supplied by Suburban under the recall. ATC will supply the parts kit needed to make the repairs. Repair time of 0.25 hours will be allotted for the repair. Parts will be sent out within 2 weeks of the repair request. If a customer or dealer have incurred costs for the cooktop that would have been covered with this repair, those costs will be reimbursed.

**How Remedy Component Differs from Recalled Component :** The repair kit consists of a support bracket with tape, screws, loctite and a decal identifier for the remedy of the stock number for future identification.

**Identify How/When Recall Condition was Corrected in Production :** Suburban corrected this issue on all new production/inventory as of 1/12/23 per notification received.

Recall Schedule :

Description of Recall Schedule :	Recall notification will begin on 4/17/23 and be completed by 4/21/23. Owners will be notified via first class mail. Dealers will be notified via email with return receipts
Planned Dealer Notification Date :	APR 17, 2023 - APR 21, 2023
Planned Owner Notification Date :	APR 17, 2023 - APR 21, 2023

\* NR - Not Reported