

Recall 23V-123 Milled Handbrake Lever Pivot

Deliver stops STOP340009 and STOP320004 have been changed to 0000321300

BMW has determined after thorough inspection that the STOP340009 for the KM3 M 1000 R Brake calipers and STOP320004 for the S 1000 RR Milled Handbrake levers have the same repair and have been consolidated to 0000321300 Recall 23V-123 Milled Handbrake Lever Pivot.

First batch of parts will be arriving in the CDC mid-March.

A recall bulletin is being produced and will be available soon.

NHTSA STATEMENT

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motorcycle covered by this notification until the recall repair has been performed. This means that dealers may not legally deliver new motorcycles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act. Also, you should not sell, lease or deliver any used motorcycles subject to a safety recall until the repair is completed. Please follow any special instructions that we provide to you for the return or disposition of recall parts.

Mar 3, 2023