

U.S. Department of Transportation

National Highway Traffic Safety Administration

May 4, 2023

Ms. Liz Jones Tiffin Motorhomes, Inc. 105 2nd Street NW Red Bay, AL 35582 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107KL 23V-308

Subject: Condensation Pan Overflow May Cause Fire

Dear Ms. Jones:

This letter serves to acknowledge Tiffin Motorhomes, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TIFFIN/ALLEGRO BREEZE/2020-2023

Mfr's Report Date: May 1, 2023

NHTSA Campaign Number: 23V-308

Components:

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER

Potential Number of Units Affected: 242

Problem Description:

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain 2020-2023 Breeze motorhomes. The condensation pan under the refrigerator may overflow and leak into the Molex electrical connections on the floor.

Consequence:

Water in the electrical connections can increase the risk of a fire.

Remedy:

Dealers will relocate the Molex connectors, free of charge. Owner notification letters are expected to be mailed June 26, 2023. Owners may contact Tiffin customer service at 1-256-356-8661. Tiffin's number for this recall is TIF-130.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

The total number of products potentially containing the defect or noncompliance (49 CFR 573.6 (c)(3)).

AMENDED 573 REQUIRED.



The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Tiffin Motorhomes, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

