



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 5, 2023

Mr. Stephen Worrall
Bentley Motors, Inc.
2200 Ferdinand Porsche Drive
Herndon, VA 02116

NEF-107DM
23V-314

Subject: Rear Entertainment Screen Bracket May Fail

Dear Mr. Worrall:

This letter serves to acknowledge Bentley Motors, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BENTLEY/FLYING SPUR/2021-2023

Mfr's Report Date: May 3, 2023

NHTSA Campaign Number: 23V-314

Components:

STRUCTURE:CRITICAL FASTENERS

Potential Number of Units Affected: 1,659

Problem Description:

Bentley Motors, Inc. (Bentley) is recalling certain 2021-2023 Flying Spur vehicles. The rear entertainment screen retention bracket, located in the rear of the front seats, may have been incorrectly installed.

Consequence:

An incorrectly installed retention bracket can result in the entertainment screen becoming a projectile during a crash, increasing the risk of occupant injury.

Remedy:

Dealers will inspect and replace the retention brackets in both front seats, as necessary, free of charge. Owner notification letters are expected to be mailed June 5, 2023. Owners may contact Bentley customer service at 1-800-777-6923. Bentley's number for this recall is RE23/06 (RC71).

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Bentley Motors, Inc.'s contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement