

Part 573 Safety Recall Report

23V-315

Manufacturer Name : Capacity of Texas**Submission Date :** MAY 03, 2023**NHTSA Recall No. :** 23V-315**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Capacity of Texas

Address : 401 Capacity Drive

Longview TX 75604

Company phone : 999

Population :

Number of potentially involved : 39

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Capacity TJ Series

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Vehicles subject to this recall are equipped with a jump seat supplied by Seats, Inc. that may not have a safety clip installed.

Production Dates : AUG 16, 2022 - NOV 10, 2022

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The jump seat on the passenger side may be missing a safety clip that prevents the pivot rod from sliding. Without this safety clip, the pivot rod could shift, causing the seat to fall.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : : A seat falling could increase the risk of an injury.

Description of the Cause : Missing safety clip.

Identification of Any Warning that can Occur : This could occur without warning.

Involved Components :

Component Name 1 : Jumper Seats

Component Description : Passenger side trainer seat

Component Part Number : 10002843

Supplier Identification :

Component Manufacturer

Name : Adam Lindloff

Address : 1515 Industrial Street
Reedsburg Wisconsin 53959

Country : United States

Chronology :

On March 15, 2023, Capacity of Texas was notified by NHTSA that Seats, Inc. identified Capacity of Texas as a purchaser of the equipment that is mentioned in this recall.

Capacity of Texas began an investigation and initially determined that it did not have a suspect population of the equipment in question. This was relayed to NHTSA.

After further investigation and communication with the supplier, it was determined that there was a population of defective units used in certain models of vehicles manufactured by Capacity of Texas.

On April 25, 2023, a defect investigation report (DIR) was drafted and escalated to the REV Group Corporate Compliance Department for approval. On May 2, 2023, the DIR was approved.

On May 3, 2023, Capacity of Texas filed a 573.

Description of Remedy :

Description of Remedy Program : Seats Inc. has issued a TSB on the repair procedure. Capacity of Texas is working with Seats Inc. to determine a remedy program for the non compliance. Meanwhile Seats Inc. has agreed to inspect suspect trucks in the field.

How Remedy Component Differs from Recalled Component : Missing clips are being installed on seats not equipped with them.

Identify How/When Recall Condition was Corrected in Production : This information has not been reported by Seats Inc.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAY 26, 2023 - JUN 02, 2023

Planned Owner Notification Date : MAY 26, 2023 - JUN 02, 2023

* NR - Not Reported